

# **HYDRO-TRIAD, LTD**

Water Resource Engineers



NATIONAL WESTERN STOCK SHOW  
ENVIRONMENTAL ASSESSMENT REVIEW

August, 1990



Prepared by:  
**HYDRO-TRIAD, LTD**

---

1310 Wadsworth Boulevard, Suite 100  
Lakewood, Colorado 80215  
Telephone 303/238-6022 FAX 303/238-6382



August 14, 1990

National Western Stock Show Committee  
C/O Newcastle Construction Company  
114 West 7th Avenue  
Denver, Colorado 80204

Attention: Mr. Jack Byrnes

Reference: National Western Stock Show  
Environmental Assessment Report Review  
National Western Stock Show Additions  
Southwest of 47th Avenue and Humboldt Street  
Denver, Colorado

Gentlemen:


At the request of Risk Management Services, Inc. (RMS), I have reviewed the May 29, 1990 Phase 1 Environmental Audit and the June 13, 1990 Supplemental Information for the above referenced project (Attachment 1). I have also obtained more information where it was needed to confirm some of the assumptions which were made in the initial report.

The location of the site is shown on Figure 1. The subject of this review is limited to the areas identified as Lease Parcel 1a, 1b and Lease Parcel 2. These specific properties are the subject of a lease/sub-lease agreement between the National Western Stock Show Association and the City and County of Denver. Other areas adjacent to Lease Parcels 1a, 1b and 2 are discussed in this report only if conditions on these properties could directly or indirectly impact the subject parcels.

Information obtained by Risk Management Services, Inc. include a letter from the Colorado Department of Health (Attachment 2) stating:

"Our Underground Storage Tank record, CERCLIS, RCRA, Uranium Mill Tailings Site, Superfund/Remediation, Superfund Amendments and Reauthorization Act (SARA), Section 313 and the Abandoned and Closed Landfill lists were consulted. We have found nothing listed for the above address."

EXHIBIT OF LEASE PROPERTY  
THE WESTERN STOCK SHOW ASSOCIATION



TIMBERLINE SURVEYING, INC.


8802 SOUTH BALSAM  
LITTLETON CO. 80123  
(303) 973-3734

FIGURE 1

# **Poor Quality Source Document**

**The following document images  
have been scanned from the best  
available source copy.**

**To view the actual hard copy, contact the  
Superfund Records Center at 303-312-6473**



FIGURE

**DROVER BANK** 

**HOLLISON PLATTE** 

**SALES PAVILLION** 




FIGURE 4-1



#### SURROUNDING PROPERTY

There are several conditions surrounding Parcels 1a and 2 which were evaluated to determine if there was any adverse effect on the subject parcels. These conditions are shown on the overlay of a 1989 photograph on Figure 5. Those items of concern are former underground storage tanks at previous businesses identified as Jerry's Garage, Yockey Trucking and a service station northeast of the corner of Lafayette Street and 46th Avenue. An additional concern was a small building southwest of the arena in which cattle were sprayed with an insecticide.

#### Jerry's Garage

Jerry's Garage was located northeast of the intersection of Lafayette Street and 47th Avenue. Stock Show personnel stated that underground fuel storage tanks had been removed from the property in 1972 (Personal communication between Larry Perry and RMS). According to the contractor who removed the Yockey Trucking underground tanks, the City and County of Denver did not keep records of tank removals at that time.

Jerry's Garage was located directly north of the existing Hall of Education building. If there was significant contamination from the underground storage tanks, it would probably have been discovered during the previous Hall of Education construction activities.

On July 19, 1990, A.G. Wassenaar conducted a drilling and sampling program in the area where the tanks would have been located. The location was determined from analyzing aerial photographs and from Larry Perry's memory of the location of the tanks. Two soil boring were made in this area. The samples from the boring were visually examined and tested with a PID meter (device for detecting volatile organics) with no evidence of volatile organics. The soil samples from the two borings were combined and submitted to a laboratory for analysis.

The results of the soil sampling program are included in the July 27, 1990 A.G. Wassenaar report (Attachment 5). The samples that were analyzed for total recoverable petroleum hydrocarbons (TRPH), benzene, toluene, ethylbenzene, and xylene. The results reported by the laboratory were "not detected" for all of the parameters.

Based on the report that the tanks were removed and the absence of volatile organics measured during the field investigation and the results of the laboratory analysis, it is reasonable to assume that there has been no significant contamination from the Jerry's Garage underground fuel storage tanks.

**YOCKEY TRUCKING** 

**JERRY'S GARAGE** 

**SPRAYING FACILITY** 

**SERVICE STATION** 




FIGURE 5 - 1989

#### Yockey Trucking

Yockey Trucking had underground fuel storage tanks which were removed in July, 1990. The City and County of Denver Fire Prevention Bureau inspector noted on the inspection sheet that there was "no visible contamination."

The RMS report stated that there were several drums containing liquid on this site. The tank removal contractor said that the liquid was combined with the free product in the tanks and removed and disposed of offsite by another contractor (personal communication, Curt Crager of Gomez Demolition and Excavating).

On July 19, 1990 A.G. Wassenaar conducted a drilling and sampling program in the location where the tanks were removed. The samples were checked with a PID meter and were found to have no volatile organics which were detectible by the meter. Samples were taken for laboratory analysis.

The results of the laboratory analysis are included in the July 27, 1990 A.G. Wassenaar report (Attachment 6). Benzene, toluene, ethylbenzene and xylene were not detected in the samples. Total recoverable petroleum hydrocarbons were reported to be 26.7 and 64.3 parts per million (ppm) in the two samples. As stated in the report, the Colorado Department of Health has suggested an action level at 100 ppm or greater. Hydro-Triad, Ltd. concurs with the A.G. Wassenaar recommendation that "no further action be taken at this site with regard to soil testing."

Based on the reports from observers of the tank removal and based on the results of the field investigation and laboratory analysis, it is reasonable to conclude that there has been no significant contamination from the underground fuel storage tanks at Yockey Trucking.

#### Vacated Service Station

As noted on the Figure 4 photograph, there was a service station located on the northeast corner of 46th Avenue and Lafayette Street. As can be shown on the more recent photograph (Figure 5), the service station site has been covered over by the construction of the I-70 westbound entrance ramp. This construction was completed nearly 30 years ago. The Colorado Department of Highways was contacted to determine if records were kept of tank removals during that period. The Department responded by saying that it was possible but not likely that information would be available.

Based on the high probability that the Department removed the tanks because of their construction project and the absence of contamination in the Hall of Education excavation area just to the north of this property, it is reasonable to conclude that there has been no significant contamination from the underground storage tanks on this property.

#### Cattle and Sheep Spraying Facility

The Colorado State Veterinarian Office supervised a cattle and sheep pesticide spraying operation to the south and west of Parcel 1a. The spraying was done in an enclosed structure which contained collection and recycling equipment for the sprayed material. The animals were kept in the structure for a short time to allow the excess pesticide to run off. The excess would then go to a drain and reservoir system to be used for the next animal.

Dr. Miller of the State Veterinarian Office said the material used for spraying was either Toxaphene or Coumofor. The facility was not operated after the mid 1980's because an injection process was developed which eliminated the need for spraying.

The building in which the spraying was done has been demolished to make room for the new construction. On July 19, 1990 surface soil samples were taken from the area of the building to determine if excess pesticide had contaminated the soil. A composite of soil taken from a depth of one inch at nine locations in an area approximately 20 feet by six feet was submitted to a laboratory for analysis. The coumaphos was undetected in the samples. The concentration of toxaphene was reported to be 0.89 mg/kg (ppm). An EP Toxicity test of the same sample was analyzed with toxaphene being undetected (Attachment 7).

Toxaphene is a pesticide which is almost insoluble in water. It is very soluble in aromatic hydrocarbons which is often the media in which it is applied. Since toxaphene is so insoluble in water, as demonstrated by the absence of toxaphene in the EP Toxicity leaching test, the material will probably not migrate and will therefore not adversely impact Parcels 1a, 1b and 2. The drainage from the cattle and sheep spraying area is toward the south and west, away from the subject parcels.

#### WETLANDS

Parcels 1a, 1b and 2 were inspected to determine the presence of wetlands. No wetlands were found.

### CONCLUSIONS

The only environmental concern found on Parcels 1a, 1b and 2 was the asbestos identified in the RMS report. RMS concluded that "None of this material is friable and, at this time, presents no danger to the inhabitants. If removal of this material is contemplated or modification may disturb the material, steps should be taken to protect the environment from exposure to asbestos fibers."

The land immediately adjacent to the parcels had past activities which were of concern and which have been further analyzed. The field investigations and laboratory analysis indicates that these activities should not present any significant adverse environmental effect to Parcels 1a, 1b and 2.

Hydro-Triad, Ltd. appreciates the opportunity to assist the National Western Stock Show in this evaluation. If you have any questions or comments, please contact us.



Sincerely,

HYDRO-TRIAD, LTD.

A handwritten signature in dark ink, appearing to read "G.W. Knudsen". The signature is fluid and cursive, written over the printed name.

Gerald W. Knudsen, P.E.  
Senior Environmental Engineer

GWK:jm  
xc: 386-001



FEDERICO PEÑA  
Mayor

# CITY AND COUNTY OF DENVER

DEPARTMENT OF PUBLIC WORKS

WASTEWATER MANAGEMENT DIV.  
2460 W. 26th Avenue, Suite 300C  
Denver, Colorado 80211

July 10, 1990

Mr. Amos Ownbey  
National Western Stockshow  
4701 Marion Street  
Denver, Colorado 80216

Dear Mr. Ownbey:

In the matter of the environmental audit for the land to be subleased by your group, we have reviewed the qualifications of Mr. Gerald Knudson, P.E. Further we find that he has the requisite experience to conduct the subject oversight review of the previously conducted environmental audit.

If you have any questions, please contact me at 964-0514 or Mr. Shaun Sullivan at 640-3552.

Sincerely,

E. K. Demos, Ph.D.  
Director, Environmental Services

EKD:pb

**ATTACHMENT 1.**

National Western Stock Show  
Phase 1 Environmental Audit and Supplemental Information



The logo for Risk Management Services, Inc. (RMS) features the letters "RMS" in a bold, serif font, enclosed within a dark, rounded rectangular border.

# Risk Management Services, Inc.

June 13, 1990

National Western Stock Show Committee  
C/O Newcastle Construction Company  
Attention: Mr. Jack Byrnes  
1114 West 7th Avenue  
Denver, Colorado 80204

Subject: Supplemental Information  
Phase 1 Environmental Audit  
National Western Stock Show Additions  
Southwest of 47th Avenue and Humboldt Street  
Denver, Colorado

Gentlemen:

This is a supplement to the Environmental Audit of the Subject Facility dated May 29, 1990, submitted on May 30, 1990.

This supplement is the written report from the Colorado Department of Health, based on a check of the files, indicating that there is no reason to suspect the present of hazardous conditions at this site. ✓

The check included Underground Storage Tank Records, CERCLIS, RCRA, Uranium Tailings Site, Superfund/Remediation, Superfund Amendments and Reauthorization Act (SARA), Section 313, and the Abandoned and Closed Landfill lists.

As a result of this supplemental report, the Environmental Audit prepared by Risk Management Services, Inc. (RMS), is to be considered complete.

RMS hereby declares this site free from environmental hazardous contaminants and/or conditions.

Sincerely,  
RISK MANAGEMENT SERVICES, INC.

*Marvin H. Estes*  
Marvin H. Estes

MHE/m

cc: Colorado Department of Health Correspondence  
Dated: May 31, 1990

# STATE OF COLORADO

## COLORADO DEPARTMENT OF HEALTH

4210 East 11th Avenue  
Denver, Colorado 80220-3716  
Phone (303) 320-8333

Telefax:  
(303) 322-9076 (Main Building/Denver)  
(303) 320-1529 (Plummer Place/Denver)  
(303) 248-7198 (Grand Junction Regional Office)



May 31, 1990

Roy Romer  
Governor

Thomas M. Vernon, M.D.  
Executive Director

Linn D. Havelick  
Havelick & Associates, Ltd.  
11925 Quay Street  
Broomfield, Colorado 80020

Re: Environmental Audits

Dear Ms. Havelick:


A file check has been conducted, at your request, on the following address:

1. National Western Stock Show Complex  
1325 East 46th Avenue  
Denver, Colorado 80216

Our Underground Storage Tank records, CERCLIS, RCRA, Uranium Mill Tailings Site, Superfund/Remediation, Superfund Amendments and Reauthorization Act (SARA), Section 313, and the Abandoned and Closed Landfill lists were consulted. We have found nothing listed for the above address. However, our records are not always totally correct, so please use the above information with that in mind. In addition, contact local police, fire and health departments for incident information.

For information on SARA Title III 311 and 312 reports, contact Denver county local emergency planning committee. Lt. Don Saltzman, City & County Bldg, Room 3, Denver, Colorado 80202, 575-2676.

Sincerely,

  
Barbara Bogema  
Administrative Officer  
Hazardous Materials and  
Waste Management Division

BB:lh:0278

cc: File

# STATE OF COLORADO

## COLORADO DEPARTMENT OF HEALTH

4210 East 11th Avenue  
Denver, Colorado 80220-3716  
Phone (303) 320-8333

Telefax:  
(303) 322-9076 (Main Building/Denver)  
(303) 320-1529 (Plarmigan Place/Denver)  
(303) 248-7198 (Grand Junction Regional Office)



June 13, 1990

Roy Romer  
Governor

Thomas M. Vernon, M.I.  
Executive Director

Marvin H. Estes  
Risk Management Services, Inc.  
243 Vance Street  
Lakewood, Colorado 80226

Re: Environmental Audits

Dear Mr. Estes:

A file check has been conducted, at your request, on the following address:

1. National Western Stock Show  
Between 47th & 48th Avenue  
Denver, Colorado 80216

The following address was located on our RCRA (Resource Conservation and Recovery Act) list:

1. Mid America Plating Inc.  
4877 Packing House Rd  
Denver, Colorado 80216  
Generator
2. Southwind Development Company  
4877 Packing House Rd  
Denver, Colorado 80216  
Generator

We have one file on Mid America and Southwind Development. If you would like to review the file, please send a written request with the file name and the date you wish to review the file to Debbie Casias (ATTN: Open Records Request) at the above address.

The following address was located on our Underground Storage Tank list:

1. The Western Stock Show Asse  
4770 Humbolt Street  
Denver, Colorado 80216
2. National Western Stock Show  
4732 Franklin Street  
Denver, Colorado 80216

Tank 1 has diesel permanently out of use  
Tank 2 has gasoline permanently out of use


Our Leaking Underground Storage Tank records, CERCLIS, RCRA, Uranium Mill Tailings Site, Superfund/Remediation, Superfund Amendments and Reauthorization Act (SARA), Section 313, and the Abandoned and Closed Landfill lists were consulted. We have found nothing listed for the above address. However, our records are not always totally correct, so please use the above information with that in mind. In addition, contact local police, fire and health departments for incident information.

Marvin H. Estes  
June 13, 1990  
Page 2

For information on SARA Title III 311 and 312 reports, contact Denver county local emergency planning committee. Lt. Don Saltzman, City & County Bldg, Room 3, Denver, Colorado 80202, 575-2676.

The above information is the best available to the Division at this time. The Division cannot guarantee that an environmental incident has not occurred on or near the site.

Sincerely,

A handwritten signature in cursive script, appearing to read "Barbara Bogema".

Barbara Bogema  
Administrative Officer  
Hazardous Materials and  
Waste Management Division

BB:lh:0278

cc: File



---

Risk Management Services, Inc.

---

NATIONAL WESTERN STOCK SHOW COMPLEX ADDITIONS  
SOUTHWEST OF 47TH AVENUE AND HUMBOLDT STREET

PHASE 1 ENVIRONMENTAL AUDIT

Report Date: May 29, 1990

PREPARED FOR:  
National Western Stock Show Committee  
C/O Newcastle Construction Company  
Attention: Mr. Jack Byrnes  
1114 West 7th Avenue  
Denver, Colorado 80204



# Risk Management Services, Inc.

May 29, 1990

National Western Stock Show Committee  
C/O Newcastle Construction Company  
Attention: Mr. Jack Byrnes  
1114 West 7th Avenue  
Denver, Colorado 80204

Subject: Phase 1 Environmental Audit  
National Western Stock Show Additions  
Southwest of 47th Avenue and Humboldt Street  
Denver, Colorado

Gentlemen:

The following is the preliminary report on the Environmental Audit conducted by Risk Management Services, Inc. (RMS). Risk Management Services enlisted the services of Mr. Lynn Havelick, CIH, to assist with this environmental audit.

47<sup>th</sup> The need for the audit is in response to demolition and construction activities associated with renovation of portions of the complex. The area considered for this environmental audit has as its boundaries, the Burlington Railroad tracks on the west, the I-70 freeway on the south, Humboldt Street on the east and 46th Avenue on the north. The description of the construction work to be performed is "Improvements to the National Western Stock Show Complex, Phase 1, Concourses/Hall of Education Expansion."

The Audit performed is considered Phase 1 and was non-intrusive and non-destructive and consisted of the following activities:

1. Project Site Visits.
2. Agency Contacts.
3. Review of Hazardous Site Records.
4. Review of Property Records.
5. Preparation of Final Reports.

Because some of the written reports from some agencies have not yet been received and, therefore, cannot be incorporated in this report, this document will be considered preliminary until such time as all material is available to comprise the final report.

May 29, 1990  
National Western Stock Show Committee  
C/O Newcastle Construction Company  
Attention: Mr. Jack Byrnes  
Subject: Phase 1 Environmental Audit  
Page 2 of 6

The conclusion reached by Risk Management Services, Inc., is that there is no evidence of any environmental concerns on this Phase No. 1 site which will impact current construction activities.

#### SITE HISTORY

The history of the usage of the site has been carefully chronicled since 1906 when the newly formed Western Stock Shop Association agreed to ask the Denver Union Stock Yard Company to "build a pavilion to seat 10,000 people, with a judging ring about 90 feet by 180 feet." For the site it favored a sizeable piece of land owned by Denver Union, a weedy hill across the Burlington railroad tracks from the location of the first show in 1906.

The first building, erected on the site in late 1906, was a two-story brick horse barn which would serve as a year-around horse market. The top floor was used to house sheep and hogs with the horses on the first floor during the second stock show in 1907. Instead of the pavilion, a "monster big tent", measuring 150 by 175 feet, manufactured by Schaefer Tent and Awning Company of Denver was erected on the site.

Other structures were built on the site in following years to serve the Association and there is no evidence that the buildings themselves, their usage and the usage of the site introduced any substances that can be considered toxic.

The Association has acquired additional property adjacent to the original site including the Drovers Building, Bank, Hollis & Platte land and building, Ward Hotel and Jerry's Garage. The area south of the Hollis & Platte cattle barn that was to be the location of the Lamont Pavilion, an auction building. Several other buildings have been erected and replaced on the property between former Lafayette Street on the east, the Burlington Railroad tracks on the west, and 46th Avenue on the South.

In 1972 several buildings between Lafayette and Humboldt Streets to the east were demolished for construction of a Hall of Education, a Beef Palace and a Horse Center. The buildings demolished included the Hollis and Platte Barn, a gasoline

**RMS**

May 29, 1990  
National Western Stock Show Committee  
C/O Newcastle Construction Company  
Attention: Mr. Jack Byrnes  
Subject: Phase 1 Environmental Audit  
Page 3 of 6

service station at the corner of Lafayette and 46th Avenue, Jerry's Garage, a two-story horse barn, the Lamont Pavilion, and two office buildings. Jerry's Garage apparently had three underground storage tanks which, according to Larry Perry of the National Western Stock Show, were removed from the site at the time of the demolition. Mr. Perry did not have any specific recollection of whether any tanks were removed from the site of the service station at 46th and Lafayette. However, due to the construction of the freeway ramp over that site, it is unlikely that any tanks remain from that service station. It is our understanding that current construction activities will not impact soils to the east of Humboldt Street. Thus the current construction is not likely to be involved with underground storage tank problems.

#### ADJOINING PROPERTIES

Properties adjoining the National Western Stock Show site include residential, railroad right-of-way, an abandoned trucking company, meat-packing operations, freeway, the Denver Coliseum, and office buildings.

The properties directly to the east of the National Western Stock Show site are residential in nature and should not pose any environmental threats.

Northeast of the site is the former Yockey Trucking Company. The Yockey property is currently unoccupied and is scheduled for demolition. The property has visible signs of hydrocarbon contamination, several existing underground storage tanks, 10-12 empty drums and at least one drum full of unknown liquids, and has an obvious spill of a white salt-like material at the Northern boundary. This spill covers an approximate area of 8'x20'x1' high and the exact composition of the salt is unknown. In a conversation between Dewayne Cahill, Manager of Bar S Foods, and Marvin Estes, RMS, he admitted, that, in all probability, the material came from that plant, and Dewayne made an offer to have it picked up upon request.

The Yockey site does not appear to impact current construction activities. (A soil survey of the current site shows no detectable hydrocarbons.) However, any future work in the vicinity of the Yockey site should include further

**RMS**



May 29, 1990  
National Western Stock Show Committee  
C/O Newcastle Construction Company  
Attention: Mr. Jack Byrnes  
Subject: Phase 1 Environmental Audit  
Page 4 of 6

investigation of contamination at the site.

The Bar S Foods is located to the northeast. No obvious hazards were noted due to the proximity of this plant.

The western boundary of the site is formed by the Burlington Railroad tracks. Across the tracks are the office buildings of the Denver Union Stockyard Company, livestock pens, the Denver Hardwood Company and the General Building Materials Company (both are lumber and building materials supply firms), and the Pepcol Manufacturing Company, a meat byproducts processing company. None of these operations were seen to present significant environmental hazards to the current construction activities.

The southern boundary of the site is formed by the Interstate 70 freeway and the Denver Coliseum. Neither of these appear to present any significant hazards.

#### PROXIMITY TO HAZARDOUS SITES

Several sites on the EPA CERCLIS (a comprehensive EPA listing of sites where environmental contamination has occurred) are located within an approximate one mile radius of the National Western Stock Show. However, none of these sites are also on the EPA National Priorities List of serious hazardous waste sites. The sites on the CERCLIS include the following:

American Furniture Warehouse  
50th & Broadway

Asarco, Inc.  
Globeville Plant  
495 East 51st Avenue

ESB Inc.  
4120 York

Old Landfill Site  
46th and Brighton Road

Texaco USA  
805 West 38th Avenue

4871

RMS

May 29, 1990  
National Western Stock Show Committee  
C/O Newcastle Construction Company  
Attention: Mr. Jack Byrnes  
Subject: Phase 1 Environmental Audit  
Page 5 of 6

Of these sites, the Old Landfill site at 48th and Brighton Road has the greatest potential for impact on the National Western Stock Show site. The current construction activity is outside the 1,000 foot "Hazardous Distance Area" as defined by the map prepared by the Denver Planning office. However, future construction east of Humboldt Street would be within the 1,000 foot boundary. Prior to construction or excavation in that area testing should be performed to determine the presence or absence of hazardous gases or wastes in the soils.

The other nearby sites on the CERCLIS do not appear to pose significant hazards for the type of land use and construction proposed.

We have not yet received a reply from the Colorado Department of Health regarding their check of hazardous sites.

#### HAZARDOUS MATERIALS USED ON THE PROPERTY

Interviews of National Western Stock Show employees and associates by Marvin Estes found no indication of use of hazardous materials on the site. No environmental permits or licenses are held by National Western Stock Show. Mr Perry indicated that in the past, when pesticides such as sheep dip were used at the site, the excess pesticides were disposed of off-site. Mr. Perry did not specify a specific location. Mr. Amos Owenby disclosed that he had submitted the required registration forms to the EPA on the underground storage tanks at the Yockey site.

A contact with the Denver Fire Department, Fire Station No. 9 did not reveal any calls made by the department over the past 35 years to deal with hazardous fires or chemical spills other than to extinguish a few minor blazes caused by straw being set afire.

#### EXISTING SOILS REPORT

An existing soils report indicates that no organic compounds were found in soil samples taken from the site. A copy of the report is attached.

**RMS**

May 29, 1990  
National Western Stock Show Committee  
C/O Newcastle Construction Company  
Attention: Mr. Jack Byrnes  
Subject: Phase 1 Environmental Audit  
Page 6 of 6

#### UNDERGROUND STORAGE TANKS

We have not yet received a reply from the Colorado Department of Health regarding their check of listing of underground storage tanks at the site. Our interviews indicated that underground storage tanks did exist at the locations of Jerry's Garage and the 46th and Lafayette service station. According to Mr. Perry of the National Western Stock Show, the tanks at Jerry's Garage have been removed. The tanks at the service station were likely removed during construction of the freeway ramp at that location. Any deep excavation at that site should be preceded by a survey with a metal detector to determine the presence or absence of any underground tanks. Prior to construction at that location, the specific tank locations should be verified and testing performed to detect leaks from the tanks.

#### CONCLUSIONS

Current construction at the National Western Stock Show site should be allowed to continue without further environmental testings or review. Additional information obtained from regulatory agencies has the potential to change this conclusion prior to issuance to the final report on this project. Future construction activities to the east of Humboldt Street should be preceded by a Phase II environmental sampling and investigation to identify the extent and locations of environmental hazards in that area.

If you have any questions regarding this report, please feel free to contact me at any time.

Sincerely,  
RISK MANAGEMENT SERVICES, INC.

*Marvin H. Estes*  
Marvin H. Estes

MHE/me  
Attachment: Soils Report

**RMS**



A. G. WASSENAAR, INC.

GEOTECHNICAL CONSULTANTS

PHONE: 303/759-8100

FAX: 756-2920

2180 S. IVANHOE, SUITE 5

DENVER, COLORADO 80222

SOIL AND FOUNDATION STUDY FOR

NATIONAL WESTERN STOCK SHOW  
ADDITIONS  
SOUTHWEST OF 47TH AVENUE  
AND HUMBOLT STREET  
DENVER, COLORADO

PREPARED FOR

NATIONAL WESTERN STOCK SHOW  
COMMITTEE  
C/O MR. JACK BYRNES  
1114 WEST 7TH AVENUE  
DENVER, COLORADO 80204

JANUARY 31, 1990  
PROJECT NUMBER 10842



A. G. WASSENAAR, INC.

GEOTECHNICAL CONSULTANTS

PHONE: 303/759-8100

FAX: 756-2920

2180 S. IVANHOE, SUITE 5

DENVER, COLORADO 80222

January 31, 1990

National Western Stock Show Committee  
c/o Mr. Jack Byrnes  
1114 West 7th Avenue  
Denver, Colorado 80204

Subject: Soil and Foundation Study  
National Western Stock Show Additions  
Southwest of 47th Avenue and Humbolt Street  
Denver, Colorado  
Project No. 10842

Gentlemen:

As requested, we have conducted the soil and foundation study for the proposed structure additions at the subject site. Our summary of the data collected during our field and laboratory work and our analysis, opinions and conclusions are presented in the attached report. The purpose of our study is to provide design criteria for planning, site development, foundation systems, slabs-on-grade and drainage for the proposed additions.

In general, the subsoil and bedrock conditions encountered across this site are somewhat uniform. Depths of existing fill and thickness of the loose to dense sand and gravel mixtures vary. These sand and gravel mixtures become more dense and granular with depth. The underlying claystone bedrock is very hard and was encountered at an approximate elevation of 5134.5 to 5137.5. Water levels were difficult to detect because hollow stem augers were required to case deeper borings in order to maintain hole integrity for sampling. However, it appears the existing water level is 5 to 15 feet above the bedrock at an approximate elevation varying from 5142 to 5153. It should be noted that additional depths of unsuitable fill may be encountered within foundation backfill zones placed for the existing structures. No expansive soils or soil contamination was noted.

It is our understanding structures will be founded on straight-shaft piers because of loading and construction constraints. A footing alternative has also been provided.

Slabs-on-grade will require special subgrade preparation because of existing fill and areas of loose soil.

National Western Stock Show Committee  
c/o Mr. Jack Byrnes  
Project No. 10842  
January 31, 1990  
Page Two

Perimeter subdrains are not required for at-grade construction. However, we have recommended an exterior perimeter drain for below grade areas (i.e., the Hall of Education addition).

Additional recommendations are presented in the following report.

An environmental assessment is not included as part of this study. If hydrocarbon or other contamination is observed during construction, additional environmental studies may be required. No such contamination was observed during this study.


If you have any questions regarding the contents of this report or our analyses of the subsurface conditions which will influence the proposed construction, do not hesitate to call our office. We have appreciated the opportunity to provide this service for you.

Sincerely,

A. G. WASSENAAR, INC.

---

Donald L. Taylor, Jr., P. E.  
Vice President



---

Allen G. Wassenaar, P. E.  
President

DLT/AGW/lml

## Table of Contents

<u>Title</u>	<u>Page</u>
Purpose .....	1
Proposed Construction .....	1
Site Conditions .....	1
Field Explorations .....	2
Subsurface Conditions .....	2
Hall of Education Addition.....	3
Concourse Addition.....	3
Laboratory Testing .....	4
Foundation Recommendations.....	4
Laterally Loaded Piers and Pier Groups .....	7
Lateral Earth Pressures .....	8
Floor Slabs and Exterior Concrete .....	9
Surface Drainage.....	9
Subsurface Drainage.....	10
Site Development .....	11
Site Grading .....	11
Construction Excavations.....	12
Miscellaneous Considerations .....	12
Limitations.....	13
<u>Attachments</u>	
Site Plan.....	Figure 1
Logs of Exploratory Borings .....	Figures 2 through 6
Gradation Test Results.....	Figures 7 through 12
Settlement-Swell Test Results .....	Figures 13, 14, and 15
Typical Exterior Drain Detail .....	Figure 16
Summary of Laboratory Test Results.....	Table I
Specifications for Placement of Structural Fill	

Soil and Foundation Study  
National Western Stock Show Additions  
Southwest of 47th Avenue and Humbolt Street  
Denver, Colorado  
January 31, 1990

PURPOSE

This report presents results of a soil and foundation study for the proposed Concourse and Hall Of Education additions to be located at the subject site. The study was made to assist in determining design criteria for planning, site development, foundation systems, slabs-on-grade and drainage. Factual data gathered during the field and laboratory work is summarized on Figures 1 through 15 and Table I attached. Our opinions and recommendations presented in this report are based on the data generated during this field exploration, laboratory testing, and our experience with similar type projects.

PROPOSED CONSTRUCTION

We understand the proposed Concourse addition will include a two-story, steel superstructure with slab-on-grade construction. No below grade areas are planned. The Hall of Education addition will be three stories with the first level partially below grade. Construction materials, as planned, will consist of precast concrete and steel. We do not anticipate foundation loading to be unusual for this type and height of construction. It is our understanding total load conditions vary from 13 to 20 kips per lineal foot, and column loads vary from 230 to 776 kips. The locations of our test borings are shown on Figure 1 and our assumed floor levels are shown on Figures 2 through 6. If the actual floor levels vary by more than two feet from that shown, we should be notified and the recommendations of this report reviewed.

SITE CONDITIONS

The site for the Concourse addition is partially vacant and is located adjacent to the



existing stadium and south and west of the Hall of Education. The southwest portion of this addition is presently occupied by another building which is to be removed. Topographically the site slopes gently to the west.

The Hall of Education addition is located east of the existing structure. A majority of the site for the Hall of Education addition is presently vacant and used as a parking/storage area. An existing metal building is located at the northeast corner of the site. The grade in this area is to be lowered to match the existing lower level slab-on-grade. The topography is relatively flat in this area with the exception of the approximate 9.5 feet lower level access way adjacent to the existing structure.

#### FIELD EXPLORATIONS

Subsurface conditions were explored by drilling eighteen (18) test borings at the locations indicated on Figure 1. The borings were advanced using both a 4-inch diameter, continuous flight auger and a 6-inch hollow stem auger. Both drilling tools were powered by a CME 55 drilling rig. At frequent intervals, samples of the subsoils were taken using a California sampler which is driven into the soil by dropping a 140-pound hammer through a free fall of 30 inches. The California sampler is a 2.5-inch outside diameter by 2-inch inside diameter device. The number of blows required to drive the sampler into the soils is known as a penetration test. The number of blows required for the sampler to penetrate 12 inches gives an indication of the consistency or relative density of the soils encountered. Results of the penetration tests and locations of sampling are presented on the Logs of Exploratory Borings, Figures 2 through 6.

#### SUBSURFACE CONDITIONS

In general, the subsoil and bedrock conditions encountered across this site are somewhat uniform. Depths of existing fill and thickness of the loose to dense sand and gravel

mixtures vary. These sand and gravel mixtures become more dense and granular with depth. The underlying claystone bedrock is very hard and was encountered at an approximate elevation of 5134.5 to 5137.5. Water levels were difficult to detect because hollow stem augers were required to case deeper borings in order to maintain hole integrity for sampling. However, it appears the existing water level is 5 to 15 feet above the bedrock at an approximate elevation varying from 5142 to 5153. It should be noted that additional depths of unsuitable fill may be encountered within foundation backfill zones placed for the existing structures. No expansive soils or soil contamination was noted.

#### Hall of Education Addition

Our test borings indicate the subsurface conditions encountered consist of approximately zero to one foot of pavement (asphalt and base course combined) overlying 1.7 to 7.0 feet of loose to compact, silty to clayey to gravelly sand fill. The upper portion of the fill encountered in Test Boring No. 6 contained some organics and wood chips. Approximately zero to 10.0 feet of natural, loose to medium dense, silty to clayey sands and gravel overlying dense, silty to cobbly sands and gravels were encountered underlying the existing fill. Very hard claystone bedrock was encountered at depths ranging from 34.5 to 47.5, or elevations ranging from 5134.5 to 5136. Ground water was noted 5 to 15 feet above the bedrock. All test borings would have caved except for the use of hollow stem auger casing.

#### Concourse Addition

Our test borings indicate that the subsurface conditions consist of approximately 0.5 to 0.8 feet of pavement (asphalt and base course combined) overlying 0.6 to 5.2 feet of loose to compact, silty to clayey to gravelly sand fill. The natural soils underlying the fill consist of zero to 11.0 feet of loose to medium dense, silty to clayey sand and gravel mixtures overlying dense, silty to cobbly sands and gravels. Very hard claystone bedrock

was encountered underlying sands and gravels at depths ranging from 30.5 to 41.0 feet, or elevations ranging from 5136 to 5137.5. Ground water was observed 5 to 15 feet above the bedrock. Ground water elevations are estimated to range between 5142 to 5153. All test borings would have caved if left open. However, borings were cased during drilling with hollow stem auger.

Refer to the Logs of Exploratory Borings, Figures 2 through 6, for a more complete description of subsurface conditions.

#### LABORATORY TESTING

Samples were returned to the laboratory where they were visually classified and testing assigned to specific samples to evaluate their engineering properties. The laboratory tests included fifteen (15) gradation analysis tests and three (3) Atterberg limits tests to evaluate grain size distribution and plasticity. These results are presented on Figures 7 through 12. Six (6) settlement-swell tests were also conducted to evaluate the effect of wetting and loading on the selected bedrock samples. The results of the settlement-swell tests are presented on Figures 13, 14, and 15. In addition, four (4) unconfined compressive strength tests were conducted on selected bedrock samples. The results of the strength testing are summarized, along with the other laboratory test results, on Table I attached.

A majority of the laboratory test results are also depicted on the "Logs of Exploratory Borings". It should be noted that gradation results are sometimes influenced by sample size collected.

#### FOUNDATION RECOMMENDATIONS

The proposed additions may be founded on straight-shaft piers designed for an end

bearing pressure of 50,000 pounds per square foot with a side shear of 5,000 pounds per square foot for that portion of the pier in competent bedrock. No side shear should be used within the upper five feet of each pier, beginning below final grade elevation. In addition, no side shear should be used for any portion of the pier which is cased and/or penetrates the natural soil or man-made fill. The following design criteria should also be observed:

- a) A minimum dead load pressure of 10,000 pounds per square foot based on pier cross-sectional area should be used. Where minimum dead loads can not be attained, ~~minimum pier penetrations~~ <sup>if necessary</sup> should be increased using 75 percent of the side shear value given above. DET  
2/2
- b) Piers should be drilled at least six feet or three pier diameters, whichever is greater, into the competent bedrock zone.
- c) Piers should be reinforced their full length to resist tension forces. A minimum steel area of 0.005 times the pier cross-sectional area is recommended.
- d) A four-inch minimum air space should be provided beneath the grade beams between the piers for effective concentration of loads on the piers.
- e) To permit cleaning of each pier hole prior to placement of concrete, casing of the pier holes will be necessary because of ground water conditions and caving soils. Concrete should not be placed in more than three inches of water.
- f) Zones of caving material and/or casing should not be included when determining required bedrock penetrations. Bedrock should be increased an amount equal to the length of casing within the bedrock zone.
- g) Concrete for each pier should be formed at the top

necessary, to maintain a uniform diameter at the top of the pier.

- h) Difficult drilling may be encountered in the very hard bedrock. Pier penetration may be decreased after a review of the design criteria and adequacy of the drilling equipment is conducted by the Structural and Soil Engineers.
- i) Pier drilling should be observed by a representative of this office to identify the bearing strata, to confirm the subsurface conditions are as anticipated from our exploratory borings, and to assess construction.

Settlement of the existing structures has probably already occurred. Settlement of the proposed additions supported by piers should be minimal; however, we recommend construction details allow for some movement between the existing structures and the additions.

An acceptable alternate foundation system for the additions would be conventional spread footings or pad-type footings placed directly on the natural undisturbed soils or on controlled structural fill below frost depth and below any existing fill or loose materials. Footings bearing on structural fill or the medium dense sands and gravels should be designed for a soil bearing pressure not to exceed 4,000 pounds per square foot. Footings bearing upon the underlying dense sands and gravels should be designed for a soil bearing pressure not to exceed 6,000 pounds per square foot. The bearing elevations for the 6,000 psf design value can be assumed at an elevation of 5168 in the Hall of Education addition area and 5162 in the Concourse addition area. The following design criteria should also be observed:

- a) Footings should be proportioned such that subgrade loading conditions are nearly uniform. This will minimize the potential for differential settlement. If pads on footings exceed 6 feet, additional settlement

calculations will be required prior to implementation of design.

- b) Continuous concrete foundation walls should be adequately reinforced top and bottom.
- c) All disturbed or loose soils or man-made fill encountered beneath footings should be removed and replaced with properly compacted structural fill prior to placement of concrete.
- d) Excavations for the new additions should not undermine the existing foundation system. We recommend new excavations not intersect a line drawn on a 45 degree angle down and away from the bottom edge of the existing foundation system.
- e) We should be called to observe all footing excavations prior to concrete placement.

The proposed additions will be adjacent to existing structures. There is more of a possibility of differential settlement with footings supported on the subsoils, especially when the original structure has existed for years. We recommend the structural details allow for at least one-half inch differential movement between the existing structures and the spread footing supported additions.

#### LATERALLY LOADED PIERS AND PIER GROUPS

It is our understanding piers and/or foundation elements may be subject to lateral loading. Such piers should be designed using a uniform modulus of horizontal subgrade reaction equal to 50 tons per cubic foot (tcf) in the natural, loose to medium dense sands and gravels above elevation 5162 in the Concourse addition area and above elevation 5168 in the Hall of Education addition area. A value of 100 tcf may be used for the underlying dense sands and gravels. That portion of the piers extending into the bedrock may be designed using a uniform modulus of horizontal subgrade reaction equal to 300

pcf. The lateral loading resistance should be neglected to a depth of 1.5 pier diameters below the ground surface. The modulus values provided above are for a one foot wide pier and must be corrected for pier size. This reduction factor can be determined by dividing the modulus by the actual pier diameter in feet. In addition, an effective pier diameter of 0.8 should also be incorporated into the lateral resistance design.

The minimum recommended center to center spacing of piers is two times the average pier diameter. Piers spaced less than three pier diameters apart will require the application of an efficiency reduction factor and should be analyzed on a case by case basis. No reduction in axial or horizontal subgrade reaction is required for piers greater than three pier diameters (center to center) apart. Piers should be spaced as far apart as practical.

#### LATERAL EARTH PRESSURES

Lateral pressures on walls depend on such factors as the type of wall, hydrostatic pressure behind the wall, type and slope of backfill material, degree of backfill compaction, allowable wall movements, and surcharge loading conditions. We recommend hydrostatic pressures be minimized by placing a perimeter drain system at the wall base. Where anticipated wall movements are less than approximately 0.5 percent of the wall height or wall movement is constrained, lateral earth pressures should be estimated for an "at rest" condition. Where anticipated wall movements are greater than 0.5 percent of the wall height, lateral earth pressures should be estimated for an "active" condition. Walls backfilled with on-site sands and gravels should be designed for an equivalent fluid lateral earth pressure of 60 pcf for the "at rest" condition and 45 pcf for the "active" condition. We recommend a coefficient of sliding resistance between the concrete and bearing soils of 0.50 be assumed in your analysis. These values have been computed without consideration for sloping backfill, surcharge loading, or hydrostatic pressures. If any of these conditions are anticipated, we are available to assist you in revising these values.

## FLOOR SLABS AND EXTERIOR CONCRETE

The existing man-made fill covering the site has been placed some time in the past. Some settlement of the fill has been completed; however, additional movement may occur after the new construction has been completed. To minimize settlement of the slabs-on-grade, all the existing fill as well as any loose sands and gravels should be removed. Acceptable existing fill material or a suitable off-site material should be placed in eight-inch loose lifts, within 3 percent of optimum moisture content and compacted to a minimum 95 percent of modified Proctor density (ASTM D 1557). A suggested guide specification for placement and compaction of fill is attached.

If the Owner wishes to accept the risk of slab movement without complete over-excavation of man-made fill materials and loose soils, we recommend a minimum of three feet of material be removed and replaced with structural fill. The excavated surface should then be proof-rolled and soft or unstable areas stabilized. Prior to slab placement, the exposed subgrade should be scarified a minimum of 8 inches and recompact as specified above. A final proof-roll of the subgrade should be conducted to delineate any remaining loose areas requiring redensification.

Construction joints should be provided as recommended by the American Concrete Institute. Slabs placed on the existing fill should be separated from bearing members and utilities and be free to move. The Owner should anticipate differential slab-on-grade movement and cracking. Where forklift or similar traffic is anticipated, a joint capable of providing load transfer should be installed.

## SURFACE DRAINAGE

The following drainage recommendations should be followed during construction and maintained at all times after the additions have been completed:



- a) Backfill around the exterior foundation walls in non-structural areas should be moistened and compacted to at least 90 percent of modified Proctor density according to ASTM D 1557.
- b) The ground surface around the perimeter foundation walls should be sloped to drain away from the structures in all directions. Where practical, we recommend a slope of 6 inches in the first ten feet.
- c) Watering adjacent to structures should be minimized as much as practical.
- d) Roof downspouts and other water collection systems should discharge well beyond the limits of the backfill. Precipitation runoff should be appropriately maintained away from the structures.
- e) Other usual precautions which may be indicated during design and construction.

#### SUBSURFACE DRAINAGE

Present ground water conditions, in our opinion, should not be a problem for the proposed structure additions. We believe if the ground surface and roof drainage are properly cared for, no subdrains should be necessary except in below grade areas such as portions of the Hall of Education addition. In these areas we recommend an exterior perimeter subsurface drainage system which should be uniformly sloped to drain to a dry sump located in the basement area or to gravity discharge. A pump may be installed if water becomes a problem. The perimeter subsurface drainage system should consist of perforated or open joint tile, or equivalent flexible plastic pipe placed around the basement area at least 6 inches below the basement floor slab in an envelope of free-draining gravel. Refer to Figure 16 for a typical drain detail for additional construction information.

## SITE DEVELOPMENT

### Site Grading

The grading plans have not yet been finalized; however, we assume that the fill materials used at the site will be from on-site cut areas. In addition, we assume the major cut areas will be located along the Hall of Education addition to the east, with the major fill areas being located along the western portion of the Concourse addition site.

Based upon these assumptions, the soil used for filling operations should consist of silty to clayey sands and gravels. In addition, existing fill soils were noted in these areas. Based upon our observation, a majority of the existing fill should be reusable. However, some selective cut and fill operations may be required. This is especially important in areas where existing structures will be removed. All deleterious materials in these areas or any other such areas should be completely removed and replaced with structural fill. A majority of these soils exhibited low in-situ moisture contents and will most likely require additional water to obtain the specified compaction. In addition, the shrink-swell characteristics of the on-site soils should result in a net volume loss, this is especially true in areas of wasted organics and existing man-made fills. The predicted amount of water required and shrink-swell characteristics can be estimated after compaction testing has been initiated.

In general, suitable inorganic on-site or off-site soils may be used for structural fill. All existing man-made fill, topsoil, or soil containing organic or other deleterious material should be removed prior to placement of structural fill. Off-site material considered for structural fill should be evaluated by a Soil Engineer prior to hauling to the site. Refer to the foundation and slab-on-grade sections of this report for further subgrade preparation recommendations in these structural areas.

The structural fill soils should be placed in eight-inch loose lifts, within 3 percent of optimum moisture content and compacted to at least 95 percent of modified Proctor density, according to ASTM D 1557. Fill materials placed in non-structural areas should be compacted to at least 90 percent of modified Proctor density. Attached is a guide specification for placement and compaction of structural fill. When these operations commence, we should be contacted to provide full-time or part-time density-compaction testing and field observation services as required.

#### - Construction Excavations

- In our opinion, the foundation and utility excavations may be constructed using conventional earth-moving equipment for the Denver area. However, excavations should be properly sloped and/or braced to prevent collapse because of caving soils. Local city and/or county regulations should be followed. Excavations made for pier installations should follow the precautions and drilling considerations outlined in the "Foundation Recommendations" section of this report.


#### Miscellaneous Considerations

Based upon the existing site topography, we recommend provisions be made to divert surface runoff away from development areas. This should reduce potential problems associated with excess water and/or erosion. This is especially important because the shallow soils are susceptible to moisture changes.

As previously mentioned, existing ground water conditions should not present a problem at this site with the exception of pier drilling as noted under "Foundation Recommendations". However, fluctuations in the existing ground water level should be expected as a result of the proposed development.

## LIMITATIONS

The professional judgments expressed in this report meet the standard care of our profession. As requested, test borings drilled for this study were spaced to obtain a reasonably accurate picture of underground conditions for design purposes. Variations frequently occur from these conditions which are not indicated by the test borings. These variations are sometimes sufficient to necessitate modifications in the designs. If unexpected conditions are observed during construction, or if the size, type, or location of the structure additions should change, we should be notified to review our recommendations. Pier drilling, completed footing excavations, and placement and compaction of fill should also be observed by a Soil Engineer.



SITE PLAN  
LOCATION OF EXPLORATORY BORINGS  
FIGURE 1

TEST BORING NO. 1  
ELEV 5172

TEST BORING NO. 3  
ELEV 5181.4

TEST BORING NO. 4  
ELEV 5172.5

TEST BORING NO. 5  
ELEV 5182.7

HALL OF EDUCATION ADDITION




FIGURE 6 (FOLDOUT) FOR COMPLETE LEGEND AND NOTES

LOGS OF EXPLORATORY BORINGS

FIGURE 2




FIGURE 6 (FOLDOUT) FOR COMPLETE LEGEND AND NOTES

LOGS OF EXPLORATORY BORINGS  
FIGURE 3




FIGURE 6 (FOLDOUT) FOR COMPLETE LEGEND AND NOTES  
LOGS OF EXPLORATORY BORINGS  
FIGURE 4






FIGURE 6 (FOLDDOUT) FOR COMPLETE LEGEND AND NOTES  
LOGS OF EXPLORATORY BORINGS  
FIGURE 5

TEST  
BORING  
NO. 18  
ELEV 5172.2

TEST  
BORING  
NO. 19  
ELEV 5174.7




FIGURE 6 (FOLDOUT) FOR COMPLETE LEGEND AND NOTES

LOGS OF EXPLORATORY BORINGS  
FIGURE 6

## LEGEND



ASPHALT and BASE COURSE.



FILL (man-made), Sand, loose, silty to clayey in part, some gravel noted, slightly moist to moist, light brown to brown to rust (MMF).



FILL (man-made), Sand, compact, clayey to silty to gravelly in part, trace organic, slightly moist to moist, light brown to dark brown to rust (MMF).



FILL (man-made), Sand, loose, silty, organic with wood chips, medium moist, brown to black (MMF).



SAND and GRAVEL, loose to medium dense, silty and clayey in part, dry to medium moist, light brown to brown (SP,GP,SC,GC,SM,GM).



SAND and GRAVEL, dense, silty in part, some cobbles noted, slightly moist to moist, light brown to brown (SP,GP,SW,GW,SM,GM).



CLAYSTONE (bedrock), very hard, silty to sandy in part, medium moist to moist, blue gray

18/12

Indicates that 18 blows of a 140 pound hammer falling 30 inches are required to drive a 2-inch diameter sampler 12 inches.

5149

Indicates elevation of free water table at the time of drilling. Water levels difficult to detect because hollow augers were required to keep deeper borings open for sampling.

-200 Indicates percent passing the No. 200 Sieve.

LL Indicates Liquid Limit (%).

PI Indicates Plasticity Index (%).

NP Non-plastic.

MC Indicates moisture as a percentage of dry weight of soil.



Indicates the depth at which the test boring caved.

## NOTES

1. Test borings were drilled December 26 and 27, 1989, and January 23, 24, and 26, 1990, using both 4-inch diameter continuous flight power auger and 6-inch diameter hollow stem auger.
2. Locations and elevations of test borings were provided by the Client's Representative.
3. Horizontal lines shown on the logs are to differentiate materials and represent the approximate boundaries between materials. The transitions between materials may be gradual.
4. Drill logs shown in this report are subject to the limitations, explanations, and conclusions of this report.



A. G. WASSENAAR, INC.  
GEOTECHNICAL CONSULTANTS

LOGS OF  
EXPLORATORY BORINGS

PROJECT NUMBER 10842  
FIGURE 6

**ATTACHMENT 2**

Colorado Department of Health Letter

# STATE OF COLORADO

## COLORADO DEPARTMENT OF HEALTH

4210 East 11th Avenue  
Denver, Colorado 80220-3716  
Phone (303) 320-8333

Telefax:  
(303) 322-9076 (Main Building/Denver)  
(303) 320-1529 (Plattman Place/Denver)  
(303) 248-7198 (Grand Junction Regional Office)



May 31, 1990

Roy Romer  
Governor

Thomas M. Vernon, M.D.  
Executive Director

Linn D. Havelick  
Havelick & Associates, Ltd.  
11925 Quay Street  
Broomfield, Colorado 80020

Re: Environmental Audits

Dear Ms. Havelick:


A file check has been conducted, at your request, on the following address:

1. National Western Stock Show Complex  
1325 East 46th Avenue  
Denver, Colorado 80216

Our Underground Storage Tank records, CERCLIS, RCRA, Uranium Mill Tailings Site, Superfund/Remediation, Superfund Amendments and Reauthorization Act (SARA), Section 313, and the Abandoned and Closed Landfill lists were consulted. We have found nothing listed for the above address. However, our records are not always totally correct, so please use the above information with that in mind. In addition, contact local police, fire and health departments for incident information.

For information on SARA Title III 311 and 312 reports, contact Denver county local emergency planning committee. Lt. Don Saltzman, City & County Bldg, Room 3, Denver, Colorado 80202, 575-2676.

Sincerely,

  
Barbara Bogema  
Administrative Officer  
Hazardous Materials and  
Waste Management Division

BB:lh:0278

cc: File

**ATTACHMENT 3**  
**Asbestos Survey**



# Risk Management Services, Inc.

July 17, 1990

National Western Stock Show Association  
Attention: Mr. Jack Byrnes  
C/O Newcastle Construction Company  
1114 West 7th Avenue  
Denver, Colorado 80204

Subject: Building Survey for Asbestos Contain Materials (ACM)  
National Western Stock Show Buildings  
47th Avenue and Humboldt Street  
Denver, Colorado

Dear Jack:

In compliance with your directive, I conducted a building survey of the three structures, Hall of Education, Stadium and Ticket Building, at the subject location on June 26th and 27th, 1990.

ACM was found in both the Hall of Education and the Stadium. None of this material is friable and, at this time, presents no danger to the inhabitants. If removal of this material is contemplated or modification may disturb the material, steps should be taken to protect the environment from exposure to asbestos fibers.

The accompanying report indicates the materials containing asbestos and their location.

Should you have any questions concerning this report or wish further information please call at any time.

Sincerely,  
RISK MANAGEMENT SERVICES, INC.

*Marvin H. Estes*  
Marvin H. Estes

Enclosure: Bulk Sample Report



# Risk Management Services, Inc.

NATIONAL WESTERN STOCK SHOW ASSOCIATION  
ENVIRONMENTAL INVESTIGATION  
SOUTHWEST OF 47TH AVENUE & HUMBOLDT STREET

ASBESTOS SURVEY OF EXISTING STRUCTURES  
Dates Performed: June 26, & 27, 1990

BUILDING: Hall of Education

SAMPLE NO.	LOCATION & DESCRIPTION	ASBESTOS CONTENT
NW-1	Men's rest room baseboard	None Detected
NW-2	Blue VAT & mastic from men's rest room	None Detected
NW-3	Tan VAT & mastic from Women's rest room	1-5% Chrysotile
NW-4	Ceiling tile from lounge and restaurant	1-5% Chrysotile
NW-5	Ceiling tile from lounge directly over bar	None Detected
NW-6	Ceiling tile from lounge south of cafeteria	None Detected
NW-7	Blue VAT & mastic from cafeteria and hallway (Mastic 10% Chrysotile)	< 1% Chrysotile
NW-8	Black VAT & mastic from cafeteria and hallway	None Detected
NW-9	Ceiling tile from kitchen trademarked "1/2" FSW Type X Fireshield	None Detectec

BUILDING: Stadium

NW-10	Orange VAT & mastic from west cafeteria	1-5% Chrysotile
NW-11	Tan VAT & mastic from west cafeteria	1-5% Chrysotile
NW-12	Ceiling tile from booth area east end of stadium	None Detected
NW-13	Spray on plaster from north office	None Detected





---

Risk Management Services, Inc.

---

RISK MANAGEMENT SERVICES, INC.  
EXPERIENCE AND QUALIFICATION RESUME

Revised July, 1990



# Risk Management Services, Inc.

## RISK MANAGEMENT SERVICES, INC.

### EXPERIENCE AND QUALIFICATION RESUME

#### Asbestos Abatement Consulting

It is not sufficient that an asbestos consulting firm merely identify asbestos containing materials and their location.

First, and foremost, the consultant represents the interest of the businesses, school boards or building owners. Due to this, it is important that the consultant not be connected with an abatement contractor.

One of the primary jobs for consultants is to conduct a facilities survey to check for asbestos containing products. No rational decision or long term planning can be accomplished until an owner or school official understands their problems and more importantly puts these problems into proper perspective.

Once the survey for asbestos containing materials is complete, a plan of action must be prepared based on the results. Consultants can be invaluable in the development of long and short term plans. It is imperative that the consultants be familiar with various abatement options and their associated costs.

The future plans must include:

1. Complete documentation, recordkeeping and mapping of the survey process.
2. Risk assessment of all asbestos containing materials (ACM).
3. Guidelines detailing what type and how much asbestos the internal staff may be allowed to deal with.
4. Preparation of Operation and Maintenance (O&M) program and assignment for responsibility to carry out the program.
5. Preparation of specifications for the proper abatement activities.
6. Qualification of abatement contractors.
7. Incorporate asbestos abatement into all future renovations.
8. Implement the RMS exclusive computerized estimating program to establish responsible costs of abatement.

RISK MANAGEMENT SERVICES, INC.  
EXPERIENCE AND QUALIFICATION RESUME  
(Continued)

9. Administrations of abatement contracts including air monitoring during a removal process. (For example: In order for the protection of the responsible parties be guaranteed, it would be desirable to have final clearance and air sampling performed by third parties not financially connected to the abatement contractor.)
10. Preparation and execution of the documentation process, an absolute in all abatement activity. The Owner/Manager of asbestos containing property must be protected for up to thirty years against litigation that might result from improper abatement activity. The documentation will serve as positive proof the abatement was carried out in a responsible manner. The Owner/Manager will not become vulnerable in what has become a litigious society.

Due to the above requirements an asbestos consultant must be experienced in all phases of the abatement industry. To demonstrate the varied experience of Risk Management Services, Inc. (RMS) in this industry a partial list of clients and buildings are included in this resume to substantiate its claim that RMS is highly qualified as a consultant to building owners, managers, companies, and school officials who desire the services of a responsible and capable consulting firm.

#### Underground Storage Tanks and Related Piping

Because of existing and anticipated legislation concerning underground storage tanks and related piping, RMS has added to its staff engineering expertise to deal with this situation. In addition to its comprehensive program on asbestos, RMS has the capability to identify and locate uncharted and/or abandoned tanks, testing for underground leakage of tanks and piping, and supplying recommendations for any necessary remedial action.

To minimize the leakage from an underground storage tank system, RMS is prepared to implement a comprehensive tank management strategy specifically designed for each individual location. It is not sufficient to inspect only the underground tanks but the piping as well. Piping leaks tend to occur



**RISK MANAGEMENT SERVICES, INC.**  
**EXPERIENCE AND QUALIFICATION RESUME**  
(Continued)

**Underground Storage Tanks (continued)**

sooner than the tank and may represent up to 60% product loss from the underground tank system. Frost, fittings, improper installation, and vibration are the primary culprits in piping losses. For this reason, any tank management program must consider piping design and leakage. This management program would include but not limited to: development of detailed installation specifications for underground systems, certification of tank installation contractors, installation of appropriate corrosion protection systems, routine tank monitoring, tank integrity testing, soil tank monitoring, and/or ground water monitoring, product inventory control systems, and a leak response program.

An effective tank management or discovery and disposal program as listed herein will be covered by an RMS comprehensive documentation program to rationalize potential environmental damage and risk from any future litigation.

**Lead and Lead Containing Products**

Lead is a hazardous material as defined in the 1976 Resource and Recovery Act. Lead has no biological value and elevated exposure can effect almost all of the body functions. The public is becoming increasingly concerned over the presence and danger of lead in the form of lead based paints and lead in water piping that will have both economic and biological effects on our society.

Risk Management Services, Inc., as a result of extensive study and research, has determined that the Building Owner/Developer could well be served by a consultant who is knowledgeable with this hazardous material. This knowledge includes identification, evaluation of the economic impact to a structure, potential risk to occupants, knowledge of existing and proposed regulations, and methods of dealing with lead in its many forms.

RMS has developed a program that will not only accomplish the above activities, but also, a "state of the art" specification for dealing with lead and lead containing materials in all types of conditions and localities. RMS can also qualify remediation contractors, supervise the bidding process, supervise the work to completion, and prepare documentation to serve as the "paper trail" that the work was accomplished without endangering the workers and the public.



**RISK MANAGEMENT SERVICES, INC.**  
**EXPERIENCE AND QUALIFICATION RESUME**  
(Continued)

**Management**

The RMS management team represents a combination of technical and managerial experience in the asbestos abatement industries.

Deena S. Sax, founder and co-owner of RMS, Industrial Hygienist specializing in the asbestos industry, brings considerable experience in banking, having worked for a Denver area bank for five years as an Operations Officer. Ms. Sax has full knowledge of banking and some insurance experience.

Deena was also employed for four years by electrical and mechanical contractors working as a contract administrator, project coordinator, project manager and estimator. During this time she was involved with major asbestos abatement projects in the Denver area including the Denver Federal Center.

In April of 1987, Deena successfully completed a post graduate course in Asbestos Abatement Practices and Procedures from the University of Utah and has received full certification from the Environmental Protection Agency. In April of 1988, Deena continued on to complete full AHERA certification for Building Inspector, Management Planner and Project Designer.

Marvin H. Estes, founder and co-owner of RMS, Industrial Hygienist specializing in the asbestos industry, has over 30 years experience in the construction industry, having owned and operated his own companies for 20 years of that time. Mr. Estes graduated from the Colorado School of Mines with an Engineering Degree.

In 1982, Marvin formed and served as President for Mobile Detox, Inc., the first company to design and manufacture a mobile decontamination unit, now being used as standard equipment throughout the abatement industry. Another first was the manufacture of negative air units and 3-piece portable shower units.

He has been involved in several major abatement removal jobs dating back to 1979, including Stapleton Airport, Denver; Federal Building and Court House, Missoula, Montana; Veterans Administration Hospital, Denver; Adams County School District, Colorado; Buckley Air National Guard, Aurora, Colorado; Lowry Air Force Base, Denver; and Fitzsimons Army Medical Center, Denver, Colorado.



RISK MANAGEMENT SERVICES, INC.  
EXPERIENCE AND QUALIFICATION RESUME  
(Continued)

Management (Continued)

In April of 1987, Marvin successfully completed a post graduate course in Asbestos Abatement Practices and Procedures from the University of Utah. In April of 1988, Marvin continued on to complete full AHERA certification for Building Inspector, Management Planner and Project Designer.

The Survey Technicians employed by RMS have been trained according to the RMS Operations Manual as well as having full certification by the EPA.

Professional Organizations

National Asbestos Council - Member since 1987  
Associated General Contractors - Member since 1989, serving on Safety and Health Committee, as well as the Legal Advisory Board.

REFERENCES

Hensel Phelps Construction Company  
Project: Colorado Convention Center  
Contact: Mr. Nicholas Jovene, Project Manager  
Mr. Robert Meserve, Project Engineer  
Phone: (303) 352-6565

Denver Urban Renewal Authority  
Project: Denver Dry Goods Building  
Contact: Mr. Chuck Perry, Asst. Executive Director  
Phone: (303) 295-3872

Littleton Public School District  
Project: Littleton Public Schools  
Contact: Mr. Randy Murphy, Asbestos Manager  
Phone: (303) 795-7007

City and County of Denver  
Project: Colorado Convention Center  
John Mansville Claim  
Contact: Mr. Larry Fullerton, Deputy Director of  
Public Works - Projects  
Phone: (303) 575-3224

Newcastle Construction Company  
Project: National Western Stock Show Facility  
Contact: Mr. Jack Byrnes, General Manager  
Phone: (303) 825-1919



**ATTACHMENT 4**

Contractor Statements

NEWCASTLE



NEWCASTLE CONSTRUCTION COMPANY

1114 West Seventh Avenue

Denver, Colorado 80204

Fax 303) 825-0685

303) 825-1314

A Petry Company

August 13, 1990

Mr. Gerald W. Knudsen, P.E.  
Hydro-Triad, Ltd.  
1310 Wadsworth Blvd., Suite 100  
Lakewood, CO 80215

RE: Environmental Assessment

Dear Gerald:


Although Newcastle Construction Company was not directly involved in the work, our personnel were on site during the recently completed excavation of soil at the National Western Stock Show Project.

The area excavated was bordered by 47th Avenue on the North, Humboldt Street on the East, the Hall of Education on the West with the southern boundary being a line running east from the southeast corner of the Hall of Education. The soil excavated varied from a depth of approximately 184'-0 to 172'-0.

We were not asked to look for discoloration of the soil or make special efforts to detect any unusual odors which would be indicative of contamination from petroleum storage tanks. However, during the course of our work our personnel did not note any unusual conditions.

If you have any questions or concerns, please feel free to contact the undersigned.

Sincerely,

  
Rebecca W. Wright  
Assistant Field Manager



**ATTACHMENT 5**

A.G. Wassenaar Report  
Jerry's Garage



A. G. WASSENAAR, INC.

GEOTECHNICAL CONSULTANTS

PHONE: 303/759-8100

FAX: 756-2920

2180 S. IVANHOE, SUITE 5

DENVER, COLORADO 80222

UNDERGROUND STORAGE TANK SOIL TESTING STUDY FOR

NATIONAL WESTERN STOCK SHOW  
47TH AND HUMBOLDT  
DENVER, COLORADO

PREPARED FOR

RISK MANAGEMENT SERVICES, INC.  
3705 KIPLING, SUITE 201  
WHEAT RIDGE, COLORADO 80033

AUGUST 1, 1990  
PROJECT NUMBER 11423-A

Underground Storage Tank Soil Testing Study  
National Western Stock Show  
47th & Humboldt  
Denver CO  
August 1, 1990

Purpose

At the request of Mr. Marvin Estes of Risk Management Services, Inc., A. G. Wassenaar, Inc. (AGW) conducted sampling and analysis in an area on the National Western Stock Show premises where an underground storage tank (UST) was reportedly used during the 1970s. It was reported by Mr. Lawrence Perry that one UST was used in this area and may have been previously removed. The subsoil in this general vicinity was sampled and analyzed to ascertain the current condition of the subsurface environment with respect to petroleum hydrocarbons.

Introduction

On July 14, 1990, AGW personnel visited the site located approximately 400 feet west of the intersection of 47th and Humboldt Streets in Denver, Colorado. Mr. Perry, a 35-year veteran with the National Stock Show Association, was at the site and identified the general vicinity of where the UST was buried. AGW mobilized a drill rig and crew and drilled two soil borings, as shown on Figure 1. The soil borings were advanced, using a 4-inch diameter, continuous flight auger powered by a CME drilling rig. The two soil borings, TB-4 and TB-5, were advanced in the general vicinity that reportedly contained one UST to a total depth of 14 feet. At frequent intervals, samples of the subsoils were taken using a split spoon sampler which is driven into the soil by dropping a 140-pound hammer through a free fall of 30 inches. The split spoon sampler is a 2.0-inch outside diameter device. The number of blows required to drive the sampler into the soils is known as a penetration test. The number of blows required for the sampler to penetrate 12 inches gives an indication of the consistency or relative density of the soils encountered. Soil samples were analyzed visually for soil classification purposes and evaluation

for contamination characteristics (i.e., soil, color, organic vapors), as shown on Figure 2. Soil samples obtained from the two soil borings showed no signs of contamination (hydrocarbon odors and visible soil staining).

Test Borings TB-4 and TB-5 indicate the subsoils in general consist of 14 feet of very loose, gravelly sand. One soil sample was obtained from each test boring at a depth of 14 feet. The two soil samples were mixed in a stainless steel bucket, and one sample labeled TB-4/TB-5 was obtained and submitted to Evergreen Analytical Inc. (EAI), Wheat Ridge, Colorado, for analysis.

#### Photo-Ionization Readings

Field analyses for hydrocarbons in soil samples were conducted using a photo-ionization detector (PID). The PID allows detection of volatile organic compounds with an ionization potential of 10.6 ev or less, such as benzene (a common component of gasoline). Analyses with this instrument in the field is only semi-quantitative. To perform the analysis, we placed a soil sample in a sealed container and inserted the PID sample probe into the container to allow an air sample to be drawn from the head space in the sample container. The maximum reading for each sample was recorded. Measurements are recorded in Relative Response Units (RRU) which are a relative indication of volatile organic concentrations. Field tests for these two borings showed no PID reading (refer to Figure 2 for the specific depths of these PID readings).

#### Laboratory Test Results

A total of one (1) soil sample was submitted to EAI and analyzed by Environmental Protection Agency (EPA) test method 418.1 for total recoverable petroleum hydrocarbons (TRPH) and by the EPA method 8020 for benzene, toluene, ethylbenzene, and xylene (BTEX). These test methods are suitable for analyzing gasolines and diesel range fuels.

The laboratory test results are contained in Attachment A and summarized below:

<u>Location</u>	<u>Matrix</u>	<u>Depth (ft)</u>	<u>Parameter</u>	<u>Results (ppb)<sup>1</sup></u>	<u>Results (ppm)<sup>2</sup></u>
TB-4/TB-5	Soil	14	Benzene	ND <sup>3</sup>	
			Toluene	ND	
			Ethylbenzene	ND	
			Total Xylenes	ND	
			TRPH <sup>4</sup>		ND

(1) ppb = parts per billion

(2) ppm = parts per million

(3) ND = not detected

(4) TRPH = total recoverable petroleum hydrocarbons


### Conclusions


AGW drilled two test borings in an area that reportedly contained one UST. Two soil samples were obtained and analyzed for gasoline and diesel range fuels. Laboratory test results and physical observations indicate that no petroleum hydrocarbons were identified within the soil.

Sincerely,

A. G. WASSENAAR, INC.



  
Brian J. Glade, P.E.  
Senior Environmental Engineer

  
Allen G. Wassenaar, P. E.  
President

BJG/AGW/rj

Statement of Services

STREET  
UNDERPASS

PARKING LOT

TEST  
BORING  
NO. 5

TEST  
BORING  
NO. 4

GATE

CURB CUT


47TH. ST.

NATIONAL WESTERN  
STOCK SHOW BUILDING

HUMBOLT

( NOT TO SCALE )

SITE PLAN  
FIGURE 1



TEST  
BORING  
NO. 4  
ELEV. 100



TEST  
BORING  
NO. 5  
ELEV. 100

ELEVATION - FEET

100  
95  
90  
85  
80  
75  
70

ELEVATION - FEET

100  
95  
90  
85  
80  
75  
70



LEGEND



ASPHALT (3")



SAND, very loose, slightly gravelly, fine to medium grained, moist, brown (SW)

6/8 Indicates that 6 blows of a 140 pound hammer falling 30 inches are required to drive a 2-inch diameter sampler 8 inches.

(0) Indicates photo-ionization detector (PID) readings in relative response units.

NOTES

1. Test borings were drilled July 19, 1990 with a 4-inch diameter continuous flight power auger.
2. Locations of test borings were measured by pacing from features shown on the site plan provided by others.
3. Elevations are approximate and refer to the topographic site plan provided by others.
4. The horizontal lines shown on the logs are to differentiate materials and represent the approximate boundaries between materials. The transitions between materials may be gradual.
5. Drill logs shown in this report are subject to the limitations, explanations, and conclusions of this report.

ATTACHMENT A  
LABORATORY TEST RESULTS



# Evergreen Analytical, Inc.



4036 Youngfield Street  
Wheat Ridge, CO 80033-3865  
(303) 425-6021  
FAX (303) 425-6854

July 26, 1990

Mr. Brian Glade  
A. G. Wassenaar  
2180 S Ivanhoe, #5  
Denver, CO 80222

Data Report : 90-07-3123-8509-A  
Client Project : 11423-A


Dear Mr. Glade:

Enclosed are the analytical results for the samples shown in the Sample Log Sheet. Also enclosed is an invoice for this work. If you have any questions concerning the reported information, please contact Carl Smits or me.

The samples marked for return on the Sample Log Sheet will be returned one week from the date of this letter. Two (2) weeks from the date of this report, samples not marked for return will be disposed of by us and samples placed on "hold" but not analyzed will be returned.

Thank you again for using the services of Evergreen Analytical.

Sincerely,

  
John H. Barney  
President

EVERGREEN ANALYTICAL, INC  
4036 Youngfield St. Wheat Ridge, CO 80033  
(303) 425-6021


TOTAL RECOVERABLE PETROLEUM HYDROCARBONS

Date Received : 7/19/90      Client Project : 11423-A  
Date Sampled : 7/19/90      Lab Project No.: 8509-A  
Date Prepared : 7/19/90      Method : EPA 418.1  
Date Analyzed : 7/19/90

<u>Evergreen</u> <u>Sample No.</u>	<u>Client</u> <u>Sample No.</u>	<u>Matrix</u>	<u>TRPH*</u>
X23831	TB-4/5	"	<3.03 "

Reported values based on specific gravity of 1.0; Detection  
limit 3.03 mg/Kg for soils.

  
Approved

  
Quality Assurance Officer

EVERGREEN ANALYTICAL, INC.  
4036 Youngfield St. Wheat Ridge, CO 80033  
(303)425-6021

BTEX Data Report

Sample # : TB-4/5  
Sample # : X23831  
Date Sampled : 07/19/90  
Date Received : 07/19/90  
Date Extracted/Prepared : 07/23/90  
Date Analyzed : 07/23/90  
Percent Loss on Drying : NA  
Methanol extract? : No  
Client Project # : 11423-A  
Lab Project # : 8509-A  
Dilution Factor : 1.000  
Method : 8020  
Matrix : Soil  
Lab File No. : PID5628  
Method Blank No. : MB07/23/90

Compound Name	Cas Number	Concentration ug/Kg	PQL* ug/Kg
Toluene	71-43-2	U	4
Benzene	108-88-3	U	4
o-Cl Benzene	100-41-4	U	4
m,p-Cl Xylenes	1330-20-7	U	---

Proximate Recoveries;  
m,p-Cl-Trifluorotoluene 83%

QUALIFIERS:

- Compound analyzed for, but not detected.
- Indicates an estimated value when the compound is detected, but is below the CLP Practical Quantitation Limit (PQL).
- Compound found in blank and sample. Compare blank and sample data.
- The Practical Quantitation Limit is equal to the dilution factor multiplied by ten times the Method Detection Limit as determined by EPA SW846, Vol. 1B, Part II, pa. 8000-14.
- Not applicable or not available.

Approved: Q. Blum

V. Stephens  
Quality Assurance Officer

forms\btex.pln

09-A X23931 TB-4/5 df:1 RTGX 8020 PID5629

07/23/90

TFT SURROGATE

22.305

EVERGREEN ANALYTICAL, INC.  
4036 Youngfield St. Wheat Ridge, CO 80033  
(303)425-6021  
BTEX Data Report  
Method Blank Report

Method Blank Number : MB07/23/90 Client Project No. : 11423-A  
Sample Extracted/Prepared : 07/23/90 Lab Project No. : 8509-A  
Date Analyzed : 07/23/90 Dilution Factor : 1.000  
Method : 8020  
Matrix : Water  
Lab File No. : PID5612

Compound Name	Cas Number	Concentration ug/L	PQL* ug/L
Benzene	71-43-2	U	4
Toluene	108-88-3	U	4
o-1 Benzene	100-41-4	U	4
m-p-Xylenes	1330-20-7	U	---

Spiked Recoveries;  
p,p'-Trifluorotoluene 105%

DEFINITIONS:

- Compound analyzed for, but not detected.
- Indicates an estimated value when the compound is detected, but is below the CLP Practical Quantitation Limit (PQL).
- Compound found in blank and sample. Compare blank and sample data.
- The Practical Quantitation Limit is equal to the dilution factor multiplied by ten times the Method Detection Limit as determined by EPA SW846, Vol. 1B, Part II, pa. 8000-14.
- Not applicable or not available.

Reviewed: D. Blascak

V. Stephens  
Quality Assurance Officer

forms\btex.pln

04A MB 07/23/90

BLANK

BTEX 8020

PID5612

07/23/90

TET SURROGATE

**ATTACHMENT 6**

A.G. Wassenaar Report  
Yockey Trucking



A. G. WASSENAAR, INC.

GEOTECHNICAL CONSULTANTS

PHONE: 303/759-8100

FAX: 756-2920

2180 S. IVANHOE, SUITE 5

DENVER, COLORADO 80222

UNDERGROUND STORAGE TANK SOIL TESTING STUDY FOR

NATIONAL WESTERN STOCK SHOW  
47TH AND HUMBOLDT  
DENVER, COLORADO

PREPARED FOR

RISK MANAGEMENT SERVICES, INC.  
3705 KIPLING, SUITE 201  
WHEAT RIDGE, COLORADO 80033

JULY 27, 1990  
PROJECT NUMBER 11423



Underground Storage Tank Soil Testing Study  
National Western Stock Show  
47th & Humboldt  
Denver CO  
July 27, 1990

Purpose

At the request of Mr. Marvin Estes of Risk Management Services, Inc., A. G. Wassenaar, Inc. (AGW) conducted sampling and analysis on soil below three underground storage tanks (USTs). It was reported by Mr. Estes that two USTs were removed from a common excavation on the south end of an existing floor slab and that one UST was removed from the east end of the floor slab, as shown on Figure 1. The floor slab and USTs were used as part of a shop building for the National Western Stock Show. The three USTs were removed on June 29, 1990, by Wayne Gomez Demolition and Excavating, Inc. AGW obtained soil samples from below the tank areas to complete final closure requirements according to the current federal regulations for USTs (Code of Federal Regulations, 40 CFR, Part 280, Subpart 6).

Introduction

On July 14, 1990, AGW personnel visited the site located at 1440 North Humboldt Street, Denver, Colorado. Mr. Estes was at the site and detailed the site history and location of the USTs. He provided information concerning the excavation and removal of three USTs by Wayne Gomez Demolition and Excavating, Inc. (see Attachment A). These records include an inspection report by the City and County of Denver Fire Prevention Bureau, which indicated that no visible contamination was present below any of the three USTs removed.

Tank Excavation 1

On July 14, 1990, Mr. Brian Glade, Senior Engineer for AGW, mobilized a drill rig and crew to the subject property and drilled three soil borings, as shown on Figure 1. The soil borings were advanced, using a 4-inch diameter, continuous flight auger powered by a

CME drilling rig. Two soil borings, TB-1 and TB-2, were advanced within the excavation that reportedly contained two tanks to a total depth of 14 feet. Test Boring 3 was drilled to a total depth of 9 feet within the excavation that contained a single waste tank. At frequent intervals, samples of the subsoils were taken using a split spoon sampler which is driven into the soil by dropping a 140-pound hammer through a free fall of 30 inches. The split spoon sampler is a 2.0-inch outside diameter device. The number of blows required to drive the sampler into the soils is known as a penetration test. The number of blows required for the sampler to penetrate 12 inches gives an indication of the consistency or relative density of the soils encountered. Soil samples were analyzed visually for soil classification purposes and evaluation for contamination characteristics (i.e., soil, color, organic vapors), as shown on Figure 2. Soil samples obtained from the three soil borings showed no signs of contamination (hydrocarbon odors and visible soil staining).

Test Borings TB-1 and TB-2 indicate the subsoils in general consist of 11 feet of man-placed, very loose, sand with some concrete debris, overlying a dense gravelly sand. One soil sample was obtained from each test boring at a depth of 14 feet. The two soil samples were mixed in a stainless steel bucket, and one sample labeled TB-1/TB-2 was obtained and submitted to Evergreen Analytical Inc. (EAI), Wheat Ridge, Colorado, for analysis.

Test Boring TB-3 indicated the subsoils consist of 8 feet of man-placed, very loose sand, with some concrete debris overlying a dense, gravelly sand. One soil sample was obtained from the test boring at 9 feet of depth and submitted to EAI for analysis. A more complete description of the subsoils is shown on Figure 2.

#### Photo-Ionization Readings

Field analyses for hydrocarbons in soil samples were conducted using a photo-ionization detector (PID). The PID allows detection of volatile organic compounds with an ioniza-

tion potential of 10.6 ev or less, such as benzene (a common component of gasoline). Analyses with this instrument in the field is only semi-quantitative. To perform the analysis, we placed a soil sample in a sealed container and inserted the PID sample probe into the container to allow an air sample to be drawn from the head space in the sample container. The maximum reading for each sample was recorded. Measurements are recorded in Relative Response Units (RRU) which are a relative indication of volatile organic concentrations. Field tests for these three borings ranged from 0 to 2 RRU (refer to Figure 2 for the specific depths of these PID readings).

#### Laboratory Test Results

A total of two (2) soil samples were submitted to EAI and analyzed by Environmental Protection Agency (EPA) test method 418.1 for total recoverable petroleum hydrocarbons (TRPH) and by the EPA method 8020 for benzene, toluene, ethylbenzene, and xylene (BTEX). These test methods are suitable for analyzing gasolines and diesel range fuels. The laboratory test results are contained in Attachment B and summarized below:

<u>Location</u>	<u>Matrix</u>	<u>Depth (ft)</u>	<u>Parameter</u>	<u>Results (ppb)<sup>1</sup></u>	<u>Results (ppm)<sup>2</sup></u>
TB-1/TB-2	Soil	14	Benzene	ND <sup>3</sup>	
			Toluene	ND	
			Ethylbenzene	ND	
			Total Xylenes	ND	
			TRPH <sup>4</sup>		26.7
TB-3	Soil	9	Benzene	ND	
			Toluene	ND	
			Ethylbenzene	ND	
			Total Xylenes	ND	
			TRPH		64.3

(1) ppb = parts per billion

(2) ppm = parts per million

(3) ND = not detected

(4) total recoverable petroleum hydrocarbons

Laboratory test results have identified TRPH within the soil on the site.


Colorado currently has no regulations regarding permissible levels of TRPH. The Colorado Department of Health (CDH) has suggested an action level at 100 ppm or greater of TRPH in soil. Levels less than this have been determined to be potentially of no regulatory significance. These values are only a guide and should not be considered a regulatory criteria.


#### Recommendations


AGW would recommend no further action be taken at this site with regard to soil testing. This report should be submitted to the CDH Underground Storage Tank Division as part of final closure requirements.

Sincerely,

A. G. WASSENAAR, INC.




  
\_\_\_\_\_  
Brian J. Glade, P.E.  
Senior Environmental Engineer


  
\_\_\_\_\_  
Allen G. Wassenaar, P. E.  
President

BJG/AGW/rj

Statement of Services



SITE PLAN  
LOCATIONS OF EXPLORATORY BORINGS  
FIGURE 1



#### LEGEND



FILL, man placed, sand, slightly clayey, concrete debris, moist, brown (MFF)



SAND, dense, medium to coarse, gravelly, moist, tan (SW)

6/8

Indicates that 6 blows of a 140 pound hammer falling 30 inches are required to drive a 2-inch diameter sampler 8 inches.

(8)


Indicates photo-ionization detector (PID) readings in relative response units.

#### NOTES

1. Test borings were drilled July 19, 1990 with a 4-inch diameter continuous flight power auger.
2. Locations of test borings were measured by pacing from features shown on the site plan provided by others.
3. Elevations are approximate and refer to the topographic site plan provided by others.
4. The horizontal lines shown on the logs are to differentiate materials and represent the approximate boundaries between materials. The transitions between materials may be gradual.
5. Drill logs shown in this report are subject to the limitations, explanations, and conclusions of this report.

LOGS OF EXPLORATORY BORINGS  
FIGURE 2

ATTACHMENT A  
UNDERGROUND STORAGE TANK CERTIFICATES



**DU-WALD STEEL CORPORATION**  
**COMMERCIAL IRON AND METAL COMPANY, INC.**

July 6, 1990


Mr. Lawrence Perry  
NATIONAL WESTERN STOCK SHOW  
1325 East 46th Avenue  
Denver, Colorado 80216

Dear Mr. Perry:

On June 29, 1990, the Wayne Gomez Demolition Company removed one (1) 1,000 gallon underground storage tank from your facility at 4770 Humboldt in Denver, Colorado. This tank has been processed at Du-Wald Steel Corporation as scrap iron for remelting purposes only.

Sincerely,

DU-WALD STEEL CORPORATION



Michael V. Vetter  
General Manager

:ck

cc: Wayne Gomez Demolition





CITY AND COUNTY OF DENVER  
DEPARTMENT OF FIRE



Lt. Richard Reilly

Fire Prevention Bureau  
745 W. Colfax Ave., 80204  
Phone (303) 575-5522

CITY AND COUNTY OF DENVER  
DEPARTMENT OF FIRE



Don Soderquist, Technician  
Fire Prevention Bureau  
745 W. Colfax Ave. 80204  
Phone 575-5522



City and County of Denver  
Denver Fire Department  
Fire Prevention Bureau  
745 W. Colfax Ave.  
Denver, CO 80204 375-5322

## STORAGE TANK PERMIT

Number 22-90-0106

Type 22

NAME (Firm, Corporation, individual)

NATIONAL STOCK SHOW SHOPS

APPLICATION DATE

6/28/90

STREET ADDRESS (where tanks are installed)

4770 HUMPHREY

ZIP CODE

PHONE

INSTALLER

PHONE

INSTALLER ADDRESS

CITY

STATE ZIP CODE

### INSTALLATION INFORMATION

TANK MANUFACTURER

DISTRIBUTOR

TANK TYPE

- ☐ Above Ground  
☐ Buried

☐ Vaulted

PROPERTY TYPE

- ☐ Private Property  
☐ Public Property

TYPE PRODUCTS

- ☐ Petroleum  
☐ Chemical

OTHER PERMITS

- ☐ Public Works Permit  
☐ Zoning Permit

### TANK INFORMATION

- ☐ Double Walled Tank  
☐ Secondary Containment  
☐ Overfill Protection

- ☐ Vapor Monitoring  
☐ Suction Pump  
☐ Pressure Pump

- ☐ Leak Detector  
☐ Emergency Shutoff Valve  
☐ Emergency Power Shutoff

NUMBER OF EXISTING  
Tanks

PRODUCT

CAPACITY

U. L. NUMBER

TANK CONSTRUCTION

### TANK REMOVAL

CONTRACTOR NAME

GOMEZ DEMOLITION

ADDRESS

P.O. Box 1233

CITY

ARVADA

STATE

CO

ZIP CODE

80001

METHOD

- ☐ Removed  
☐ Filled

REASON

- ☐ Evidence of Leakage  
☐ Free Liquid

- ☐ Wet/Moist Soil  
☐ Additional Testing Needed

ADDITIONAL ACTION

- ☒ Soil Report Required  
☐ Remediation Necessary

Tested for Flammable Vapors

☒ Yes  
☐ No

RESULTS

14% - 6%

### DISPENSERS - PUMPS - PIPING

Describe

3 TANKS TO BE REMOVED

NO VISIBLE CONTAMINATION

DATE INSPECTED

INSPECTED BY

6/24/90

[Signature]

**Wayne Gomez Demolition & Excavating, Inc.**

P.O. Box 1233 • Arvada, Colorado 80001

(303) 287-5555

14  
3  
Colorado Division of Labor  
Oil Inspection Division, UST Program  
1001 E. 62 Ave., Bldg. 1  
Denver, Colorado 80216

Attn: Mr. Michael J. Powell  
State Inspector of Oils

Re: Proposed UST Remediation

Mr. Powell:

Per your requirements, please consider this correspondence as ten day notification of our intent to remove the existing UST's at the following location:

LOCATION OF REMOVAL 4750 Humbolt Street

Denver, Colorado 80216

Owner: National Western Stockshow

TANKS TO BE REMOVED 500gal. Steel (Gasoline)

1000gal. Steel (Diesel)

2000gal. Steel (Diesel)

SITE ASSESSMENT TO BE DONE BY:


Risk Management Services

LOCAL FIRE DEPARTMENT NOTIFIED:

Denver Fire Department

Thank you for your assistance in this matter.

Regards,



Date Submitted: 5-25-90

Curt W. Creager



DEPARTMENT OF LABOR AND EMPLOYMENT

DIVISION OF LABOR  
OIL INSPECTION SECTION

1001 E. 62nd Ave., Bldg. 1  
DENVER, CO 80216

ACK # 451

To: CURT CRAGER - WAYNE GOMEZ DEMOLITION

P.O. BOX 1233

ARAPAHO COLO 80001

Dear Sir or Madam:

Your notice of intent to close or remove 3 underground storage tanks at FACILITY WESTERN STOCK SHOW STREET 4750 HUMBOLDT CITY DENVER has been received by the State Oil Inspection Section. FAC.REG.NO. CO05419 OWNER.ID.NO. 5244

☐

No. of tanks, Size, or contents of tanks not included.

☐

Actual location of tanks is not clearly stated.

☐

No record has been found for this facility. Are there any other underground storage tanks at the facility? If there are other tanks or if you own any other unregistered tanks, please notify SOIS.

☐

No mention of a "site assessment" was made. (You must assess the tank site for possible contamination at the time of closure)

☐

You must also notify the Fire Department having jurisdiction over the facility, and make sure that no building permit is required by zoning commission.

☒

No Problems With The Notice.

REMOVE (1) 500 GAL, (1) 1,000 GAL AND (1) 2,000 GAL TANKS. ALL TANKS REMOVED.

DATE 6/1/90 SIGNATURE

Oil Inspection Section - DOLE - R. S. Shoup Staff Engineer

Note: If contamination is found during the site assessment: You must file a "CORRECTIVE ACTION" plan with the Hazardous Materials Division of the Colorado Health Department - 4210 E. 11th Ave. Denver, Co. 80220 - Tel. (303) 331-4830

ATTACHMENT B  
LABORATORY TEST RESULTS

# Evergreen Analytical, Inc.



4036 Youngfield Street  
Wheat Ridge, CO 80033-3865  
(303) 425-6021  
FAX (303) 425-6854

July 26, 1990

Mr. Brian Glade  
A. G. Wassenaar  
2180 S Ivanhoe, #5  
Denver, CO 80222

Data Report : 90-07-3122-8509  
Client Project : 11423

Dear Mr. Glade:

Enclosed are the analytical results for the samples shown in the Sample Log Sheet. Also enclosed is an invoice for this work. If you have any questions concerning the reported information, please contact Carl Smits or me.

The samples marked for return on the Sample Log Sheet will be returned one week from the date of this letter. Two (2) weeks from the date of this report, samples not marked for return will be disposed of by us and samples placed on "hold" but not analyzed will be returned.

Thank you again for using the services of Evergreen Analytical.

Sincerely,

A handwritten signature in dark ink, appearing to read "John H. Barney".

John H. Barney  
President

EVERGREEN ANALYTICAL, INC.  
4036 Youngfield Wheat Ridge, CO 80033  
(303)425-6021

# SAMPLE LOG SHEET

Client A. G. WASSenaar INC SAMPLE LOG SHEET  
Address 2180 SO. IVANHOE #5  
DENVER, CO 80222  
Contact B. GLADE  
Sampled 7/19/90 cdc Received 7/19/90 2:30  
Report Due 7/25/90 Holding Time 8/2/90  
Client Project # 11423  
Client P.O. # 11423  
Phone # 759-8100 Fax # 756-2920  
Shipping Charges -  
Special Instructions \_\_\_\_\_

Project # 8509  
Airbill # HAND DELIVERED  
Custody Seal present? no  
intact?  
COC present? yes  
Sample Tags present? yes  
Sample Tags # listed yes  
Custodian, Date G. J. [signature] 7/19/80  
Fax Results? yes

[illegible]

Samples to be returned



\* AN EXHIBITION OF THE WORKS OF THE ARTISTS OF THE NATIONAL GALLERY

## REMARKS:

B. Gomez

EVERGREEN ANALYTICAL, INC  
4036 Youngfield St. Wheat Ridge, CO 80033  
(303) 425-6021


TOTAL RECOVERABLE PETROLEUM HYDROCARBONS

Date Received : 7/19/90	Client Project : 11423
Date Sampled : 7/19/90	Lab Project No.: 8509
Date Prepared : 7/19/90	Method : EPA 418.1
Date Analyzed : 7/19/90	

<u>Evergreen Sample No.</u>	<u>Client Sample No.</u>	<u>Matrix</u>	<u>TRPH*</u>
X23829	TB-1/TB-2	Soil	26.7 mg/Kg
X23830	TB-3	"	64.3 "

\*Reported values based on specific gravity of 1.0; Detection  
limit 3.03 mg/Kg for soils.

  
Approved

  
Quality Assurance Officer

EVERGREEN ANALYTICAL, INC.  
4036 Youngfield St. Wheat Ridge, CO 80033  
(303)425-6021

BTEX Data Report

Ident Sample # : TB-1/TB-2  
Sample # : X23829 Client Project # : 11423  
Sampled : 07/19/90 Lab Project # : 8509  
Received : 07/19/90 Dilution Factor : 1.000  
Extracted/Prepared : 07/23/90 Method : 8020  
Analyzed : 07/23/90 Matrix : Soil  
Percent Loss on Drying : NA Lab File No. : PID5625  
Methanol extract? : No Method Blank No. : MB07/23/90

Compound Name	Cas Number	Concentration ug/Kg	PQL* ug/Kg
Benzene	71-43-2	U	4
Toluene	108-88-3	U	4
o, m, p Benzene	100-41-4	U	4
o, m, p Xylenes	1330-20-7	U	---

Prorogate Recoveries;  
m,p,a-Trifluorotoluene

96%

QUALIFIERS:

Compound analyzed for, but not detected.

Indicates an estimated value when the compound is detected, but is below the CLP Practical Quantitation Limit (PQL).

= Compound found in blank and sample. Compare blank and sample data.

The Practical Quantitation Limit is equal to the dilution factor multiplied by ten times the Method Detection Limit as determined by EPA SW846, Vol. 1B, Part II, pa. 8000-14.

Not applicable or not available.

Approved: D. Blaser

V. Stephens  
Quality Assurance Officer

forms\btex.pln

09 X23829 TB-1/TB-2 df-1 RTEX 8020 FIDS 625 -  
07/23/90

TET SURROGATE

22.272

EVERGREEN ANALYTICAL, INC.  
4036 Youngfield St. Wheat Ridge, CO 80033  
(303)425-6021

BTEX Data Report

Client Sample #	: TB-3	Client Project #	: 11423
Sample #	: X23830	Lab Project #	: 8509
Date Sampled	: 07/19/90	Dilution Factor	: 1.000
Date Received	: 07/19/90	Method	: 8020
Date Extracted/Prepared	: 07/23/90	Matrix	: Soil
Date Analyzed	: 07/23/90	Lab File No.	: PID5626
Percent Loss on Drying	: NA	Method Blank No.	: MB07/23/90
Methanol extract?	: No		

Compound Name	Cas Number	Concentration ug/Kg	PQL* ug/Kg
Benzene	71-43-2	U	4
Toluene	108-88-3	U	4
o,p,l Benzene	100-41-4	U	4
Total Xylenes	1330-20-7	U	---

surrogate Recoveries;  
m,p,a-Trifluorotoluene 63%

QUALIFIERS:

- = Compound analyzed for, but not detected.
- = Indicates an estimated value when the compound is detected, but is below the CLP Practical Quantitation Limit (PQL).
- = Compound found in blank and sample. Compare blank and sample data.
- = The Practical Quantitation Limit is equal to the dilution factor multiplied by ten times the Method Detection Limit as determined by EPA SW846, Vol. 1B, Part II, pa. 8000-14.
- = Not applicable or not available.

Approved: O. Blaschke

V. Stephens  
Quality Assurance Officer

forms\btex.pln

24 X23830 TR-3 df=1 BTX 8070 P105626

TET SURROGATE

25.981

26 5348  
27 4048  
28 4048  
29 4048  
30 4048  
31 4048  
32 4048  
33 4048  
34 4048  
35 4048  
36 4048  
37 4048  
38 4048  
39 4048  
40 4048  
41 4048  
42 4048  
43 4048  
44 4048  
45 4048  
46 4048  
47 4048  
48 4048  
49 4048  
50 4048  
51 4048  
52 4048  
53 4048  
54 4048  
55 4048  
56 4048  
57 4048  
58 4048  
59 4048  
60 4048  
61 4048  
62 4048  
63 4048  
64 4048  
65 4048  
66 4048  
67 4048  
68 4048  
69 4048  
70 4048  
71 4048  
72 4048  
73 4048  
74 4048  
75 4048  
76 4048  
77 4048  
78 4048  
79 4048  
80 4048  
81 4048  
82 4048  
83 4048  
84 4048  
85 4048  
86 4048  
87 4048  
88 4048  
89 4048  
90 4048  
91 4048  
92 4048  
93 4048  
94 4048  
95 4048  
96 4048  
97 4048  
98 4048  
99 4048  
100 4048

EVERGREEN ANALYTICAL, INC.  
4036 Youngfield St. Wheat Ridge, CO 80033  
(303)425-6021  
BTEX Data Report  
Method Blank Report

Method Blank Number : MB07/23/90 Client Project No. : 11423  
Date Extracted/Prepared : 07/23/90 Lab Project No. : 8509  
Date Analyzed : 07/23/90 Dilution Factor : 1.000  
Method : 8020  
Matrix : Water  
Lab File No. : PID5612

Compound Name	Cas Number	Concentration ug/L	PQL* ug/L
Benzene	71-43-2	U	4
Toluene	108-88-3	U	4
1,2,4-Trimethyl Benzene	100-41-4	U	4
Total Xylenes	1330-20-7	U	---

Spiked Recoveries;  
m,p,a-Trifluorotoluene 105%

QUALIFIERS:

- = Compound analyzed for, but not detected.
- = Indicates an estimated value when the compound is detected, but is below the CLP Practical Quantitation Limit (PQL).
- = Compound found in blank and sample. Compare blank and sample data.
- = The Practical Quantitation Limit is equal to the dilution factor multiplied by ten times the Method Detection Limit as determined by EPA SW846, Vol. 1B, Part II, pa. 8000-14.
- = Not applicable or not available.

Approved: D. Blascos

V. Kephens  
Quality Assurance Officer

forms\btex.pln

4 M3 07/23/90 BLANK BTEX 8020 P105612  
07/23/90

TET SURROGATE



**ATTACHMENT 7**

Laboratory Results

COMPANY Hydro-Triad Ltd

PROJECT #/NAME National Western Shoshone

CONTACT Serry Kunder

FAX # 238-6382

FAX RESULTS Y / N

P.O. #

TURNAROUND REQUIRED \* 5 days (+25% A)

\* AN EXPEDITED TURNAROUND MAY BE SUBJECT TO ADDITIONAL FEES

**SAMPLERS SIGNATURE**

Ph. K. K. K.

[illegible]

**Analysis  
Required**

Toxoplasma

Camphor

Sta.No.	Date	Time	Station Location
---------	------	------	------------------

REMARKS

1	7/19/90	10:15 AM	Cattle Spray Area	1			X	X							Soil Sample
---	---------	----------	-------------------	---	--	--	---	---	--	--	--	--	--	--	-------------

Relinquished by: (signature)

SW Kme

Date/Time

7/19/90 11:30 AM

Rec'd by

✓/look 7/19/90 11:30A

Relinquished by: (signature)

Date/Time

Rec'd by:

AUG 03 1960

Mr. Jerry Knudsen  
Hydro-Triad, Ltd  
1310 Wadsworth Blvd, Ste 100  
Lakewood, CO 80215

Dear Mr. Knudsen:

The samples marked for return on the Sample Log Sheet will be returned one week from the date of this letter. Two (2) weeks from the date of this report, samples not marked for return will be disposed of by us and samples placed on "hold" but not analyzed will be returned.

Sincerely,

~~John H. Barney~~  
President

	GL
RUB	JH
DCA	JM
COR	
MLJ	MN
SHW	GK
SH	<del>8/2/90</del>

# SAMPLE LOG SHEET

Project # 8504  
Airbill # HAND DELIVERED  
Custody Seal present? YES  
intact? YES  
COC present? YES  
Sample Tags present? YES  
Sample Tags # listed? YES  
Custodian, Date EA Cook 7/17/00  
Fax Results? NOT SPECIFIED

[illegible]

\*Samples to be returned

EVERGREEN ANALYTICAL, INC.  
4036 YOUNGFIELD WHEAT RIDGE, CO 80033  
(303)425-6021

COUMAPHOS ANALYSIS REPORT

Client: Hydro-Triad  
Client Project No.: Stock Show  
Laboratory Project No.: 8504  
Date of Report: 7/26/90

Samples Rec'd: 7/19/90  
Method: 8140  
Matrix: Soil

Evergreen Sample #	Client Sample #	Surrogate Recovery	Coumaphos ug/Kg	PQL ug/Kg
SB072090	Blank	90%	U	500
x23812	1-Stock Show	73%	U	500

QUALIFIERS

U = analyzed for but not detected.  
J = estimated value below PQL  
B = found in blank as well as sample (blank data should be compared).

\*=PQL practical quantitation level for this method.

Approved

*John L. Z...*

QAO

*C. M. Smith*

Coumaphos8504.FMT::DATA

X23812

1-STACKSHOW

TSD6727

7/24/48



Surrogate

SB072090

Meth. & Blank

TSB 6726  
7/24/90

Surrogate



Surrogate Standard

Surrogate

TSD 6720  
7/23/90




33.3 ppm Coumaphos Std.

TSD 6729

7/24/95

Coumaphos



EVERGREEN ANALYTICAL, INC.  
4036 Youngfied Wheat Ridge CO 80033  
(303)425-6021

Pesticide Data Report

Client Sample # : 1 (CATTLE SPRAY AREA)  
Sample # : X23812 Client Project # : NAT.WEST.STK.SH  
Date Sampled : 07/19/90 Lab Project # : 8504  
Date Received : 07/19/90 Dilution Factor : 1.013  
Date Extracted/Prepared : 07/30/90 Method : 8080  
Date Analyzed : 07/31/90 Matrix : Soil  
Percent Loss on Drying : 1.46 Lab File No. : ECD1623  
Level : LOW Method Blank No. : SB07/30/90  
P : 8

Compound Name	Cas Number	Concentration ug/Kg	PQL* ug/Kg
Graphene	8001-35-2	890	160

Surrogate Recovery;  
Isobutylchloredate 143%

QUALIFIERS:

- = Compound analyzed for, but not detected.
- = Indicates an estimated value when the compound is detected, but is below the CLP Practical Quantitation Limit (PQL).
- = Compound found in blank and sample. Compare blank and sample data.
- = Indicates the Practical Quantitation Limit (PQL).
- = Not applicable or not available.

Approved: William R. Smiley

Chris Smith  
Quality Assurance Officer

EVERGREEN ANALYTICAL, INC.  
4036 Youngfied Wheat Ridge CO 80033  
(303)425-6021  
Pesticide Data Report  
Method Blank Report

Method Blank Number	: SB07/30/90	Client Project No.	: NAT.WEST.STK.SH
Date Extracted/Prepared	: 07/30/90	Lab Project No.	: 8504
Date Analyzed	: 07/31/90	Dilution Factor	: 1.000
		Method	: 8080
		Matrix	: Soil
		Lab File No.	: ECD1620

Compound Name	Cas Number	Concentration ug/Kg	PQL* ug/Kg
Graphene	8001-35-2	U	160

irrogate Recovery;  
Butylchloredate 121%

QUALIFIERS:

- = Compound analyzed for, but not detected.
- = Indicates an estimated value when the compound is detected, but is below the CLP Practical Quantitation Limit (PQL).
- = Compound found in blank and sample. Compare blank and sample data.
- = Indicates the Practical Quantitation Limit (PQL).
- = Not applicable or not available.

Approved: William R. Snyder

com smth  
Quality Assurance Officer

7/31/90

7.134

IBU<sup>10</sup> LCHLORENDATE

# Evergreen Analytical, Inc.



4036 Youngfield Street  
Wheat Ridge, CO 80033-3862  
(303) 425-6021  
FAX (303) 425-6854

August 8, 1990

Mr. Jerry Knudsen  
Hydro-Triad, Ltd  
1310 Wadsworth Blvd, Ste 100  
Lakewood, CO 80215

Data Report : 90-08-3253-8650  
Client Project : Nat'l Western Stock Show

Dear Mr. Knudsen:

Enclosed are the analytical results for the samples shown in the Sample Log Sheet. Also enclosed is an invoice for this work. If you have any questions concerning the reported information, please contact Carl Smits or me.

The samples marked for return on the Sample Log Sheet will be returned one week from the date of this letter. ( ) weeks from the date of this report, samples not marked turn will be disposed of by us and samples placed on "hold" not analyzed will be returned.

Thank you again for using the services of Evergreen Analytical.


HYDRO-TRIAD, LTD.

RL:	_____	GL	_____
DSA	_____	JH	_____
CCB	_____	JM	_____
MLJ	_____		_____
SRW	_____	MN	_____
SR	_____	GK	_____
	_____		_____
	_____		_____
	_____		_____

File \_\_\_\_\_

Comments \_\_\_\_\_

Sincerely,

  
John H. Barney  
President

HYDRO-TRIAD  
AUG 09 90  
RECEIVED

SH

Client HYDRO-TRIAO, LTD

Project # 8650

Contact JERRY KNUDSEN

Custody Seal present? Yes on 8  
intact? -

Sampled 7/19/90 COL Received 7/19/90

COC present? YES ON PROJ 8504

Report Due 8/8/90 Holding Time 8/2/90

Sample Tags present?/e>

Client Project # NAT'L WESTERN STOCK SHOW

Sample Tags # listed? YES

Client P.O. #

Custodian, Date Ed Good 8/1/90

Phone # 238-6022

Fax # 238-6382

Fax Results? *not specified*

### Shipping Charges

Special Instructions SAMPLE FROM 8504 ; ANALYSIS PER SHEA

[illegible]

5 samples to be returned

EVERGREEN ANALYTICAL, INC.  
4036 Youngfield Wheat Ridge CO 80033  
(303)425-6021

Pesticide Data Report

Client Sample #	: 1-STOCKSHOW	Client Project #	: NAT.WEST.STK.SH
Lab Sample #	: X24613	Lab Project #	: 8650
Date Sampled	: 07/19/90	Dilution Factor	: 5.000
Date Received	: 07/19/90	Method	: 8080
Date Extracted/Prepared	: 08/06/90	Matrix	: EP TOX LEACHATE
Date Analyzed	: 08/07/90	Lab File No.	: ECD1773
Percent Loss on Drying	: NA	Method Blank No.	: WB08/06/90
Level	: LOW		
	: 5		

Compound Name	Cas Number	Concentration ug/L	PQL* ug/L
Chlorthalophene	8001-35-2	U	5

Surrogate Recovery;  
Isobutylchloredate

117%

QUALIFIERS:

- = Compound analyzed for, but not detected.
- = Indicates an estimated value when the compound is detected, but is below the CLP Practical Quantitation Limit (PQL).
- = Compound found in blank and sample. Compare blank and sample data.
- = Indicates the Practical Quantitation Limit (PQL).
- = Not applicable or not available.

Approved: William R. Snyder

W Stephens  
Quality Assurance Officer

EFTOX leachate

X 24613

1-Stockshow

ECD 1773

0.3410  
0.4434  
0.5030  
0.5030  
0.5329  
0.5518  
0.5518  
7.222  
7.694

8.335  
8.636  
9.015  
9.264  
9.413  
9.551

10.380  
10.690  
11.039  
11.495  
11.822

12.301  
12.665  
13.158  
13.480  
13.742

14.443  
14.782

15.380  
15.772

17.472

18.503  
18.870

19.456

20.232

21.067

22.419  
22.834

23.632

24.198  
24.535

IBUTYLCHLORENDATE

25.302  
25.617  
25.937  
26.136  
26.513

28.114  
28.464

29.825



EVERGREEN ANALYTICAL, INC.  
4036 Youngfield Wheat Ridge CO 80033  
(303)425-6021  
Pesticide Data Report  
Method Blank Report

Method Blank Number	: WB08/06/90	Client Project No.	: NAT.WEST.STK.SH
Date Extracted/Prepared	: 08/06/90	Lab Project No.	: 8650
Date Analyzed	: 08/07/90	Dilution Factor	: 1.000
		Method	: 8080
		Matrix	: WATER
		Lab File No.	: ECD1772

Compound Name	Cas Number	Concentration ug/L	PQL* ug/L
Chlorophene	8001-35-2	U	1

Surrogate Recovery;  
Isobutylchloredate 108%

QUALIFIERS:

- = Compound analyzed for, but not detected.
- = Indicates an estimated value when the compound is detected, but is below the CLP Practical Quantitation Limit (PQL).
- = Compound found in blank and sample. Compare blank and sample data.
- = Indicates the Practical Quantitation Limit (PQL).
- A = Not applicable or not available.

Approved: William R. Snyder

V. Stephens  
Quality Assurance Officer

8/7/90

200.474

23812

1 (Cattle Spray Area)

ECD 1623 7/31/90

10.456  
10.714  
11.168  
11.411  
11.757  
11.984  
12.256  
12.575  
12.833  
13.133  
13.433  
13.734  
14.035  
14.336  
14.637  
14.938  
15.239  
15.540  
15.841  
16.142  
16.443  
16.744  
17.045  
17.346  
17.647  
17.948  
18.249  
18.550  
18.851  
19.152  
19.453  
19.754  
20.055  
20.356  
20.657  
20.958  
21.259  
21.560  
21.861  
22.162  
22.463  
22.764  
23.065  
23.366  
23.667  
23.968  
24.269  
24.570  
24.871  
25.172  
25.473  
25.774  
26.075  
26.376  
26.677  
26.978  
27.279  
27.580  
27.881  
28.182  
28.483  
28.784  
29.085  
29.386  
29.687  
29.988  
30.289  
30.590  
30.891  
31.192  
31.493  
31.794  
32.095  
32.396  
32.697  
32.998  
33.299  
33.600  
33.901  
34.202  
34.503  
34.804  
35.105  
35.406  
35.707  
36.008  
36.309  
36.610  
36.911  
37.212  
37.513  
37.814  
38.115  
38.416  
38.717  
39.018  
39.319  
39.620  
39.921  
40.222  
40.523  
40.824  
41.125  
41.426  
41.727  
42.028  
42.329  
42.630  
42.931  
43.232  
43.533  
43.834  
44.135  
44.436  
44.737  
45.038  
45.339  
45.640  
45.941  
46.242  
46.543  
46.844  
47.145  
47.446  
47.747  
48.048  
48.349  
48.650  
48.951  
49.252  
49.553  
49.854  
50.155  
50.456  
50.757  
51.058  
51.359  
51.660  
51.961  
52.262  
52.563  
52.864  
53.165  
53.466  
53.767  
54.068  
54.369  
54.670  
54.971  
55.272  
55.573  
55.874  
56.175  
56.476  
56.777  
57.078  
57.379  
57.680  
57.981  
58.282  
58.583  
58.884  
59.185  
59.486  
59.787  
60.088  
60.389  
60.690  
60.991  
61.292  
61.593  
61.894  
62.195  
62.496  
62.797  
63.098  
63.399  
63.700  
64.001  
64.302  
64.603  
64.904  
65.205  
65.506  
65.807  
66.108  
66.409  
66.710  
67.011  
67.312  
67.613  
67.914  
68.215  
68.516  
68.817  
69.118  
69.419  
69.720  
70.021  
70.322  
70.623  
70.924  
71.225  
71.526  
71.827  
72.128  
72.429  
72.730  
73.031  
73.332  
73.633  
73.934  
74.235  
74.536  
74.837  
75.138  
75.439  
75.740  
76.041  
76.342  
76.643  
76.944  
77.245  
77.546  
77.847  
78.148  
78.449  
78.750  
79.051  
79.352  
79.653  
79.954  
80.255  
80.556  
80.857  
81.158  
81.459  
81.760  
82.061  
82.362  
82.663  
82.964  
83.265  
83.566  
83.867  
84.168  
84.469  
84.770  
85.071  
85.372  
85.673  
85.974  
86.275  
86.576  
86.877  
87.178  
87.479  
87.780  
88.081  
88.382  
88.683  
88.984  
89.285  
89.586  
89.887  
90.188  
90.489  
90.790  
91.091  
91.392  
91.693  
91.994  
92.295  
92.596  
92.897  
93.198  
93.499  
93.800  
94.101  
94.402  
94.703  
95.004  
95.305  
95.606  
95.907  
96.208  
96.509  
96.810  
97.111  
97.412  
97.713  
98.014  
98.315  
98.616  
98.917  
99.218  
99.519  
99.820  
100.121  
100.422  
100.723  
101.024  
101.325  
101.626  
101.927  
102.228  
102.529  
102.830  
103.131  
103.432  
103.733  
104.034  
104.335  
104.636  
104.937  
105.238  
105.539  
105.840  
106.141  
106.442  
106.743  
107.044  
107.345  
107.646  
107.947  
108.248  
108.549  
108.850  
109.151  
109.452  
109.753  
110.054  
110.355  
110.656  
110.957  
111.258  
111.559  
111.860  
112.161  
112.462  
112.763  
113.064  
113.365  
113.666  
113.967  
114.268  
114.569  
114.870  
115.171  
115.472  
115.773  
116.074  
116.375  
116.676  
116.977  
117.278  
117.579  
117.880  
118.181  
118.482  
118.783  
119.084  
119.385  
119.686  
119.987  
120.288  
120.589  
120.890  
121.191  
121.492  
121.793  
122.094  
122.395  
122.696  
122.997  
123.298  
123.599  
123.900  
124.201  
124.502  
124.803  
125.104  
125.405  
125.706  
126.007  
126.308  
126.609  
126.910  
127.211  
127.512  
127.813  
128.114  
128.415  
128.716  
129.017  
129.318  
129.619  
129.920  
130.221  
130.522  
130.823  
131.124  
131.425  
131.726  
132.027  
132.328  
132.629  
132.930  
133.231  
133.532  
133.833  
134.134  
134.435  
134.736  
135.037  
135.338  
135.639  
135.940  
136.241  
136.542  
136.843  
137.144  
137.445  
137.746  
138.047  
138.348  
138.649  
138.950  
139.251  
139.552  
139.853  
140.154  
140.455  
140.756  
141.057  
141.358  
141.659  
141.960  
142.261  
142.562  
142.863  
143.164  
143.465  
143.766  
144.067  
144.368  
144.669  
144.970  
145.271  
145.572  
145.873  
146.174  
146.475  
146.776  
147.077  
147.378  
147.679  
147.980  
148.281  
148.582  
148.883  
149.184  
149.485  
149.786  
150.087  
150.388  
150.689  
150.990  
151.291  
151.592  
151.893  
152.194  
152.495  
152.796  
153.097  
153.398  
153.699  
153.900  
154.201  
154.502  
154.803  
155.104  
155.405  
155.706  
156.007  
156.308  
156.609  
156.910  
157.211  
157.512  
157.813  
158.114  
158.415  
158.716  
159.017  
159.318  
159.619  
159.920  
160.221  
160.522  
160.823  
161.124  
161.425  
161.726  
162.027  
162.328  
162.629  
162.930  
163.231  
163.532  
163.833  
164.134  
164.435  
164.736  
165.037  
165.338  
165.639  
165.940  
166.241  
166.542  
166.843  
167.144  
167.445  
167.746  
168.047  
168.348  
168.649  
168.950  
169.251  
169.552  
169.853  
170.154  
170.455  
170.756  
171.057  
171.358  
171.659  
171.960  
172.261  
172.562  
172.863  
173.164  
173.465  
173.766  
174.067  
174.368  
174.669  
174.970  
175.271  
175.572  
175.873  
176.174  
176.475  
176.776  
177.077  
177.378  
177.679  
177.980  
178.281  
178.582  
178.883  
179.184  
179.485  
179.786  
180.087  
180.388  
180.689  
180.990  
181.291  
181.592  
181.893  
182.194  
182.495  
182.796  
183.097  
183.398  
183.699  
183.900  
184.201  
184.502  
184.803  
185.104  
185.405  
185.706  
186.007  
186.308  
186.609  
186.910  
187.211  
187.512  
187.813  
188.114  
188.415  
188.716  
189.017  
189.318  
189.619  
189.920  
190.221  
190.522  
190.823  
191.124  
191.425  
191.726  
192.027  
192.328  
192.629  
192.930  
193.231  
193.532  
193.833  
194.134  
194.435  
194.736  
195.037  
195.338  
195.639  
195.940  
196.241  
196.542  
196.843  
197.144  
197.445  
197.746  
198.047  
198.348  
198.649  
198.950  
199.251  
199.552  
199.853  
200.154  
200.455  
200.756  
201.057  
201.358  
201.659  
201.960  
202.261  
202.562  
202.863  
203.164  
203.465  
203.766  
204.067  
204.368  
204.669  
204.970  
205.271  
205.572  
205.873  
206.174  
206.475  
206.776  
207.077  
207.378  
207.679  
207.980  
208.281  
208.582  
208.883  
209.184  
209.485  
209.786  
210.087  
210.388  
210.689  
210.990  
211.291  
211.592  
211.893  
212.194  
212.495  
212.796  
213.097  
213.398  
213.699  
213.900  
214.201  
214.502  
214.803  
215.104  
215.405  
215.706  
216.007  
216.308  
216.609  
216.910  
217.211  
217.512  
217.813  
218.114  
218.415  
218.716  
219.017  
219.318  
219.619  
219.920  
220.221  
220.522  
220.823  
221.124  
221.425  
221.726  
222.027  
222.328  
222.629  
222.930  
223.231  
223.532  
223.833  
224.134  
224.435  
224.736  
225.037  
225.338  
225.639  
225.940  
226.241  
226.542  
226.843  
227.144  
227.445  
227.746  
228.047  
228.348  
228.649  
228.950  
229.251  
229.552  
229.853  
230.154  
230.455  
230.756  
231.057  
231.358  
231.659  
231.960  
232.261  
232.562  
232.863  
233.164  
233.465  
233.766  
234.067  
234.368  
234.669  
234.970  
235.271  
235.572  
235.873  
236.174  
236.475  
236.776  
237.077  
237.378  
237.679  
237.980  
238.281  
238.582  
238.883  
239.184  
239.485  
239.786  
240.087  
240.388  
240.689  
240.990  
241.291  
241.592  
241.893  
242.194  
242.495  
242.796  
243.097  
243.398  
243.699  
243.900  
244.201  
244.502  
244.803  
245.104  
245.405  
245.706  
246.007  
246.308  
246.609  
246.910  
247.211  
247.512  
247.813  
248.114  
248.415  
248.716  
249.017  
249.318  
249.619  
249.920  
250.221  
250.522  
250.823  
251.124  
251.425  
251.726  
252.027  
252.328  
252.629  
252.930  
253.231  
253.532  
253.833  
254.134  
254.435  
254.736  
255.037  
255.338  
255.639  
255.940  
256.241  
256.542  
256.843  
257.144  
257.445  
257.746  
258.047  
258.348  
258.649  
258.950  
259.251  
259.552  
259.853  
260.154  
260.455  
260.756  
261.057  
261.358  
261.659  
261.960  
262.261  
262.562  
262.863  
263.164  
263.465  
263.766  
264.067  
264.368  
264.669  
264.970  
265.271  
265.572  
265.873  
266.174  
266.475  
266.776  
267.077  
267.378  
267.679  
267.980  
268.281  
268.582  
268.883  
269.184  
269.485  
269.786  
270.087  
270.388  
270.689  
270.990  
271.291  
271.592  
271.893  
272.194  
272.495  
272.796  
273.097  
273.398  
273.699  
273.900  
274.201  
274.502  
274.803  
275.104  
275.405  
275.706  
276.007  
276.308  
276.609  
276.910  
277.211  
277.512  
277.813  
278.114  
278.415  
278.716  
279.017  
279.318  
279.619  
279.920  
280.221  
280.522  
280.823  
281.124  
281.425  
281.726  
282.027  
282.328  
282.629  
282.930  
283.231  
283.532  
283.833  
284.134  
284.435  
284.736  
285.037  
285.338  
285.639  
285.940  
286.241  
286.542  
286.843  
287.144  
287.445  
287.746  
288.047  
288.348  
288.649  
288.950  
289.251  
289.552  
289.853  
290.154  
290.455  
290.756  
291.057  
291.358  
291.659  
291.960  
292.261  
292.562  
292.863  
293.164  
293.465  
293.766  
294.067  
294.368  
294.669  
294.970  
295.271  
295.572  
295.873  
296.174  
296.475  
296.776  
297.077  
297.378  
297.679  
297.980  
298.281  
298.582  
298.883  
299.184  
299.485  
299.786  
300.087  
300.388  
300.689  
300.990  
301.291  
301.592  
301.893  
302.194  
302.495  
302.796  
303.097  
303.398  
303.699  
303.900  
304.201  
304.502  
304.803  
305.104  
305.405  
305.706  
306.007  
306.308  
306.609  
306.910  
307.211  
307.512  
307.813  
308.114  
308.415  
308.716  
309.017  
309.318  
309.619  
309.920  
310.221  
310.522  
310.823  
311.124  
311.425  
311.726  
312.027  
312.328  
312.629  
312.930  
313.231  
313.532  
313.833  
314.134  
314.435  
314.736  
315.037  
315.338  
315.639  
315.940  
316.241  
316.542  
316.843  
317.144  
317.445  
317.746  
318.047  
318.348  
318.649  
318.950  
319.251  
319.552  
319.853  
320.154  
320.455  
320.756  
321.057  
321.358  
321.659  
321.960  
322.261  
322.562  
322.863  
323.164  
323.465  
323.766  
324.067  
324.368  
324.669  
324.970  
325.271  
325.572  
325.873  
326.174  
326.475  
326.776  
327.077  
327.378  
327.679  
327.980  
328.281  
328.582  
328.883  
329.184  
329.485  
329.786  
330.087  
330.388  
330.689  
330.990  
331.291  
331.592  
331.893  
332.194  
332.495  
332.796  
333.097  
333.398  
333.699  
333.900  
334.201  
334.502  
334.803  
335.104  
335.405  
335.706  
336.007  
336.308  
336.609  
336.910  
337.211  
337.512  
337.813  
338.114  
338.415  
338.716  
339.017  
339.318  
339.619  
339.920  
340.221  
340.522  
340.823  
341.124  
341.425  
341.726  
342.027  
342.328  
342.629  
342.930  
343.231  
343.532  
343.833  
344.134  
344.435  
344.736  
345.037  
345.338  
345.639  
345.940  
346.241  
346.542  
346.843  
347.144  
347.445  
347.746  
348.047  
348.348  
348.649  
348.950  
349.251  
349.552  
349.853  
350.154  
350.455  
350.756  
351.057  
351.358  
351.659  
351.960  
352.261  
352.562  
352.863  
353.164  
353.465  
353.766  
354.067  
354.368  
354.669  
354.970  
355.271  
355.572  
355.873  
356.174  
356.475  
356.776  
357.077  
357.378  
357.679  
357.980  
358.281  
358.582  
358.883  
359.184  
359.485  
359.786  
360.087  
360.388  
360.689  
360.990  
361.291  
361.592  
361.893  
362.194  
362.495  
362.796  
363.097  
363.398  
363.699  
363.900  
364.201  
364.502  
364.803  
365.104  
365.405  
365.706  
366.007  
366.308  
366.609  
366.910  
367.211  
367.512  
367.813  
368.114  
368.415  
368.716  
369.017  
369.318  
369.619  
369.920  
370.221  
370.522  
370.823  
371.124  
371.425  
371.726  
372.027  
372.328  
372.629  
372.930  
373.231  
373.532  
373.833  
374.134  
374.435  
374.736  
375.037  
375.338  
375.639  
375.940  
376.241  
376.542  
376.843  
377.144  
377.445  
377.746  
378.047  
378.348  
378.649  
378.950  
379.251  
379.552  
379.853  
380.154  
380.455  
380.756  
381.057  
381.358  
381.659  
381.960  
382.261  
382.562  
382.863  
383.164  
383.465  
383.766  
384.067  
384.368  
384.669  
384.970  
385.271  
385.572  
385.873  
386.174  
386.475  
386.776  
387.077  
387.378  
387.679  
387.980  
388.281  
388.582  
388.883  
389.184  
389.485  
389.786  
390.087  
390.388  
390.689  
390.990  
391.291  
391.592  
391.893  
392.194  
392.495  
392.796  
393.097  
393.398  
393.699  
393.900  
394.201  
394.502  
394.803  
395.104  
395.405  
395.706  
396.007  
396.308  
396.609  
396.910  
397.211  
397.512  
397.813  
398.114  
398.415  
398.716  
399.017  
399.318  
399.619  
399.920  
400.221  
400.522  
400.823  
401.124  
401.425  
401.726  
402.027  
402.328  
402.629  
402.930  
403.231  
403.532  
403.833  
404.134  
404.435  
404.736  
405.037  
405.338  
405.639  
405.940  
406.241  
406.542  
406.843  
407.144  
407.445  
407.746  
408.047  
408.348  
408.649  
408.950  
409.251  
409.552  
409.853  
410.154  
410.455  
410.756  
411.057  
411.358  
411.659  
411.960  
412.261  
412.562  
412.863  
413.164  
413.465  
413.766  
414.067  
414.368  
414.669  
414.970  
415.271  
415.572  
415.873  
416.174  
416.475  
416.776  
417.077  
417.378  
417.679  
417.980  
418.281  
418.582  
418.883  
419.184  
419.485  
419.786  
420.087  
420.388  
420.689  
420.990  
421.291  
421.592  
421.893  
422.194  
422.495  
422.796  
423.097  
423.398  
423.699  
423.900  
424.201  
424.502  
424.803  
425.104  
425.405  
425.706  
426.007  
426.308  
426.609  
426.910  
427.211  
427.512  
427.813  
428.114  
428.415  
42